

JAN 18 2001

Approved by Alger County
Land Survey Monumentation
Peer Group Under Act 345 of
P.A. of 1990 On 12-13-19-2000

Gerald W. Jamros
Chairman
05-220

For corners in **SECTION** **LAND CORNER RECORDATION CERTIFICATE**
Filing Requirement of Act 74, Mich. P.A. 1970

Alger
(County)

Located In:

Corner Code #

1. Public Land Survey

T 48N R 15W M.C. M08-09 ✓

T 48N R 14W M.C. A08-09

T _____ R _____

T _____ R _____

2. Property Controlling
in Section

S _____ T _____ R _____

S _____ T _____ R _____

3. Miscellaneous

S _____ T _____ R _____

Property in Section

S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

FILED
TIME 8:50 Am.

DEC 20 2000

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

I, Robert L. Jamros, in a field survey on October 19, 2000,
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, recovered, found
as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

MC M08-09: PLS William A. Burt, DS, 1841. North, 10.87 chains. Intersect lake and set
post. Tamarack 6", S.51°W., 40 links. Tamarack 7", N.84°W., 26 links. ***** No other
subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

MC M08-09: Established Meander Corner position by single proportionate measurement and 10.87
chains North of section corner to the South and on line with section corner 69.13 chains
North. No original G.L.O. evidence was found. Found 2, possibly 3 unmatching paint lines
running South from this position. Corner position as established is accepted as a careful
and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

MC M08-09: Set 2½" x 30" Berntsen aluminum monument no. A1NB30 with 31/4" aluminum cap
stamped to identify corner position. Established reference trees with BT signs, blazed,
scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following:
Hemlock 8", N.68°W., 43.44 feet (MC BT); Hemlock 6", N.75°W., 27.98 feet (MC BT); Hemlock
10", S.49°W., 50.38 feet (MC BT); Hemlock 15", S.04°E., 47.85 feet (MC BT). Survey marker
sign on 6 foot steel post, N.70°W., 1.0 feet. All bearings are magnetic.

Signed by Robert L. Jamros Date Dec. 17, 2000
Surveyor's Michigan License No. 25849

