

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 8 T 48N R 33W	5
	S 8 T 48N R 33W	8
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	10		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 5 09/30/2010 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(5-Sec. 8) North 1/16 corner, Section 8. 1993 - Established by the undersigned midway and on line
between N1/4 corner and Center of Section. Set 1"IDx32" I.pipe with 4" alum. MDNR cap. 6" Sugar
S71W 19.4', 10" Sugar N67W 29.1', 12" Sugar N26E 28.8', 5" Sugar S62E 30.5'.

(8-Sec. 8) West 1/16 corner, Section 8. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(5-Sec. 8) Found the 1993 monument in good condition and at record bearing and distance from three
of the 1993 witnesses. Made one new witness, as described below.

(8-Sec. 8) Established the corner midway and on a straight line between the West 1/4 corner of
Section 8 and the Center of Section 8, both monumented and of record.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(5) Fd. 1"ID I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
12" Sugar N65W 29.5' old marks 1993 BT
14" Sugar N28E 29.45' do do
8" Sugar S61E 30.8' do do
4" Sugar S19W 30.7' mrkd "1/16S BT"
Set sq'd cedar post adjacent.
Bearings are magnetic.

(8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
9" Sugar N14E 11.2' mrkd "1/16S BT"
6" Sugar N68E 20.75' do
8" Sugar S11W 37.2' do
10" Sugar S59W 32.95' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 01/12/2011

For the Michigan Department of Natural Resources and Environment, Forest Management Division

