## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

on this certificate.

| Baraga   | Located In:  | Corner Code #  |              |                                       |        |                  |
|--|--|--|--------------|---------------------------------------|--------|------------------|
| (County)   | <del>-</del>   |  | 50           |                                       | • 6    |                  |
| 1. Public Land Survey  | T 49N R 32W<br>T 48N R 32W<br>T R  | Name of the Control o | £.           |                                       |        |                  |
| 2. Property Controlling in Section   | S T R S T R  | (Same conten)  |              |                                       |        |                  |
| 3. Miscellaneous Property in Sec.  | S T R S T R  |  | Desister of  | Daniel Channel                        |        |                  |
| 4. Lot No. , Red<br>5. Private Claims  | corded Plat  |  | A B C D      | Deeds Stamp &                         | I J K  | L N              |
| above were in conformance with<br>instructions of the United States<br>a Court of Law and /or that the | 74, Michigan P.A. of 1970, the corregulations and rules therefore as repeatment of the Interior, Bureau corner points mentioned in lines 3, 4 d of Land Surveyors or by a De | equired in the current manual of so<br>of Land Management or by a decre<br>4 and 5 above were in conformance   | and 2 5      | , , , , , , , , , , , , , , , , , , , |        | 12-1324          |
| NOTE: Not more than 2 corn   | ners, all in the same town and ra  | ange may be recorded   | 10 - 30 - 29 | 28 2                                  | 7-1-26 | 2 <sup>'</sup> 5 |

(F13) Quarter corner common to Section 33 T49N-R32W and Section 4 T48N-R32W. 1846 - Established by W.A.Burt and Austin Burt, Deputy Surveyors, midway and on the Township line between Section corners 40.00 chains east and west. Set Fir post. Cedar 9 N67E 26 links, Cedar 16 N70W 16 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A. Description of original monument and accessories and/or subsequent restoration:

(F13) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the corner on the curved Township line and at the position proportionate to the original record between Section corners 40.00 chains east (2638.04' M) and 120.00 chains west (13185.33' M).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F13) Set 1"IDx32" I.pipe with 4" alum. MDNR cap made firm in a mound of rock. Set measuring nail with MDNR tag in the side of:

11" Cedar S01W 19.35' mrkd "1/4S NBT"

1/4 HI'KUI ...

4" Sugar N73W 15.35'

do

4" Maple N37W 10.75'

do

17" W.Pine NO8E 26.5'

do

Set sq'd cedar post adjacent.

Bearings are magnetic.



Surveyor's Michigan License No.

33986

Date

07/09/2009

Michigan Electise No.