LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	Filiti	ig Requirement of Act 13, h					
Baraga (County)	Located In:	Corner Code #					
1. Public Land Survey	T <u>50N</u> R TR TR TR						
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR STR		Regi	ister of De	eds Stamp	& File Nu	umber
4. Lot No, Reco 5. Private Claims	rded Plat		1	C D E	F G H	I J	κ ι
, Stephan J. Szyszkoski	_, in a field surveyon .	10/16/98 	tate that under 4 7-	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ -	- 4 3 9 1	0 11-	12
requirements of P.A. 74, Michig conformence with regulations and United States Department of the that the corner points mentioned	an P.A. of 1970, the come d rules therefore as require Interior, Bureau of Land M d in lines 3, 4 and 5 above y a Decree of a Court o	or points mentioned in lines 1 and 2 d in the current manual of survey inst lanagement or by a decree of a Court were in conformance with the rules of f Law; established, re-established,	above were in tructions of the of Law and for fithe Michigan	17		5 14 2 23 -	13
NOTE: Not more than 2 cor on this certificate.	ners, all in the same tow	n and range, may be recorded	9	29	-28 -2	726	25
		es and/or subsequent restoration	n: Nachh between Sections		10 00 5#	tanarark (]Î

Quarter corner common to Sections 8 & 9. Established in 1949 by Nm. A. Burt: "North between Sections 8 & 9...40.00 Set tamarack qr. section post. Tamarack 12 N66N 30, do 4 \$34E 10...80.00 Set post corner of Sections 4,5 8,9". B. Description of corner evidence found... The original post and accessories were not recovered. At the location for the corner, I found a very old barbed wire fence running westerly from an abandoned and overgrown N-S roadbed. The roadbed is defined from approximately the south 1/16 corner between 889 north to the Section corner 4-5-8-9. (continued below)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Continued from above — I traced the fence line to about 300° west of the old road and it runs quite straight at a magnetic bearing of N87M. The fence continues west but I did not follow it any farther. At the intersection of the E'ly extension of the fence with the roadbed, I find a 3/8° dia. by 8' long copper grounding rod sunk 4' into the ground. There is no fence to the east. A local land owner, Mr. Philip M. Keyes says that it is his understanding that the fence is the original homestead fence constructed 80-90 years ago and that it is regarded as the E-M 1/4 line of Sec. 8. I recover, in the roadbed, an ancient 12° iron culvert, 10.5' long, about 4' south of the corner and use it's center to define the center of the roadbed. I measure south to a recorded section corner 2597.8' over very rough terrain, and north approximately 2630' to the NM corner of section 9. The bed is about 18' M. of a line between these corners at the fence. I accept the intersection of the fence with the center of the old bed (as defined by the culvert) to be the best available evidence of the position of the original corner and place a 1°IDx32° iron pipe capped with a plastic cap stamped "MICH DHR PS 33986" at that location.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set ! pipe with plastic cap "MICH DWR OF MICH PS 33986" projecting 10". Blazed, scribed and set measuring mails in: STEPHAN J 7° 81k Spruce N76E 26.15 1/4S MBT SZYSZKOSKI 5" 81k Spruce M22E 51.05' do 7" Blk Spruce M51M 32.8' LAND SURVEYOR 5" Blk Spruce S15E 43.75' do Nα Distances are to 16d galvanized sinkers with brass tags. Bearings are magnetic. ZANDSU 33986 Surveyor's Michigan License No

For the Michigan Department of Natural Resources - Forest Management Division