

MAY 0 5 1997

Surveyor's Michigan License No. 39091

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Daraga Located In: Corner Code # DAY OF DECEMBER, 1996 AT 10:	For corners in COMM	ICCHT!	Filing Requir	ement of Act 74,	, Mich. P.A. 19	70				
1. Public Land Survey T. 60N R.3.1W. T. R. T. R				Carra Cada		RECEIVE	D FOR REC	ORD TH	IS 20	TH
1. Public Land Survey TEON R 31W TR TR TR TR TR TR TR TR TR T			ocated in:	Corner Code	: #					
2. Property Controlling S T R R R Register of Deeds Stamp & File Num 4. Lot No. Recorded Plat S T R R Register of Deeds Stamp & File Num 4. Lot No. Recorded Plat R R Register of Deeds Stamp & File Num 4. Lot No. Recorded Plat R R R Register of Deeds Stamp & File Num 4. Lot No. Recorded Plat R R R R R R R R R R R R R R R R R R R	1. Public Land Survey			A-1*		OF LAND	CORNER RI	ECORDA	TION	4
2. Property Controlling S. T. R. BARACK COUNTY REGISTER/OF DI. 3. Miscellaneous S. T. R. Register of Deads Stamp & File Num 4. Lot No						بهب	4.4	_	,	
4. Lot No	in Section	S	Γ R Γ R			BARAGA (COUNTY REC	ALSTER.	OF D	EEDS
4. Lot No. Recorded Plat 5. Private Claims 1. Michael Mileski in a field survey on November 19.96. do hereby take that under requirements of PA. 74, Michael PA. of 1970, the corner points mentioned in fines 1 and 2 above were in conformance with regulations and naise therefore as recurried in the current remailed of survey instructions of the United States Department of the Interior, Bureau of Land Management of by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 8 above were in conformance with risk the corner points mentioned in lines 3, 4 and 8 above were in conformance with risk the corner points mentioned in lines 3, 4 and 8 above were in conformance with risk the corner points mentioned in lines 3, 4 and 8 above were in conformance with risk the corner points mentioned in lines 3, 4 and 8 above were in conformance with risk the form the proportion of court of Law and for the security of the corner of the corner of the United States Department of the Interior of Court of Law and for the corner of the Court of Law and for the corner of Law and for the Court of Law and for the corner of Law and the corner of Law and the Court of Law and Law		\$				Daniet	ar of Dande S	toma &	Eila Mu	mhae
1. Michael Mileski . In a field survey on November 19 96 to hereby state that under requirements of P.A. 74. Mehigan P.A. of 1970, the corner points manifoned in lines 1 and 2 above were in confortnance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management or by a decree of a Court of Leward for that the course points manifoned in lines 1 and 2 above were in confortance with roth the course points manifoned in lines 3, 4 and 5 above were in section of aurvey instructions of the United States Department of the Interior. Bureau of Land Management or by a decree of a Court of Lang. **Statistical Court of Lang and The States Department of the Interior. Bureau of Land Management or by a decree of a Court of Lang. **Statistical Court of Lang and Court of Lang. **Statistical Court of Lang. **Not more than 2 corners, all in the same town and range, may be recorded on this certificate. **A-1; Northwest Corner Section 6, T50N, R31W; **Originally established during U.S. Survey conducted by William Burt, D.S. in 1846 and monumented with an ironwood post witnessed by a Hemlock 30 S15°E 32 lks. and a Sugar 16 S70°W 7 lks. **No subsequent record of this corner was found. **B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: **A-1; Northwest Corner Section 6, T50N, R31W; Found a 1¼ "diameter iron pipe projecting 18" above ground in the vicinity of the corner. This monumen bears \$75°E a distance of 17.23 feet from the proportioned position. This corner is not mentioned in the field notes of Norman Thompson, RLS #4348. Furthermore, there is no physical evidence of U.S. bearing tree remains from this monument. I considered the corner lost and reestablished it at the proportioned position. **C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: **A-1; Northwest Corner Section 6, T50N, R31W; Set	. ,				_	KeBisi	er of Deeds 3	tamp oci	riie Nu	mber
1. Michael Mileski . In a field survey on November 19 96 to hereby state that under requirements of P.A. 74. Mehigan P.A. of 1970, the corner points manifoned in lines 1 and 2 above were in confortnance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management or by a decree of a Court of Leward for that the course points manifoned in lines 1 and 2 above were in confortance with roth the course points manifoned in lines 3, 4 and 5 above were in section of aurvey instructions of the United States Department of the Interior. Bureau of Land Management or by a decree of a Court of Lang. **Statistical Court of Lang and The States Department of the Interior. Bureau of Land Management or by a decree of a Court of Lang. **Statistical Court of Lang and Court of Lang. **Statistical Court of Lang. **Not more than 2 corners, all in the same town and range, may be recorded on this certificate. **A-1; Northwest Corner Section 6, T50N, R31W; **Originally established during U.S. Survey conducted by William Burt, D.S. in 1846 and monumented with an ironwood post witnessed by a Hemlock 30 S15°E 32 lks. and a Sugar 16 S70°W 7 lks. **No subsequent record of this corner was found. **B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: **A-1; Northwest Corner Section 6, T50N, R31W; Found a 1¼ "diameter iron pipe projecting 18" above ground in the vicinity of the corner. This monumen bears \$75°E a distance of 17.23 feet from the proportioned position. This corner is not mentioned in the field notes of Norman Thompson, RLS #4348. Furthermore, there is no physical evidence of U.S. bearing tree remains from this monument. I considered the corner lost and reestablished it at the proportioned position. **C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: **A-1; Northwest Corner Section 6, T50N, R31W; Set	4. Lot No,	Recorded Plat								
I. Michael Mileski . In a field survey on November . 19 96. do hereby state that under requirements of P.A. 74, Michigan P.A. of 1870, the corner points manctoned in fines 1 and 2 above were in conformance with regulations and relate therefore as required in the current manual of survey instructions of the United States Department of the Intelligence of the Operation of the Intelligence of the Operation of the Conformance with Michigan Rand of Land Stunways or by a Decree of a Court of Law; established, re-established, re-established, re-established, re-established, re-established, re-established, re-established, re-established curring U.S. Survey conducted by William Burt, D.S. in 1846 and monumented with an irronwood post witnessed by a Hemlock 30 S15°E 32 lks. and a Sugar 16 S70°W 7 lks. No subsequent record of this corner was found. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: A-1; Northwest Corner Section 6, T50N, R31W; Found a 1 ½ " diameter iron pipe projecting 18" above ground in the vicinity of the corner. This monumen bears S75°E a distance of 17.23 feet from the proportioned position. This corner is not mentioned in the field notes of Norman Thompson, RLS #4348. Furthermore, there is no physical evidence of U.S. bearing tree remains from this monument. I considered the corner lost and reestablished it at the proportioned position of monument for corner and accessories established to perpetuate locating the position of the corner: A-1; Northwest Corner Section 6, T50N, R31W; Set a 1"(I.D.) x 36" galvanized iron pipe with a 2" aluminum cap stamped as to location projecting 16" above ground. Set 7" spike Ne/side 11" Sugar Maple S34°W 11.4.42 MILESKI PROFESSIONAL SURVEYOR No. Surveyor North 1.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is						1 B C	DEF	G H I	JK	L M
A. Description of original monument and accessories and/or subsequent restoration: A.1; Northwest Corner Section 6, T50N, R31W; Discription of corner evidence found and/or method applied in restoring or reestabilishing corner: A.1; Northwest Corner Section 6, T50N, R31W; Found a 1 ¼" diameter iron pipe projecting 18" above ground in the vicinity of the corner. This monumen bears S75°E a distance of 17.23 feet from the proportioned position. This corner is not mentioned in the field notes of Norman Thompson, RLS #4348. Furthermore, there is no physical evidence of U.S. bearing tree remains from this monument. I considered the corner lost and reestabilished. A. Description of monument and accessories and/or subsequent restoration: A.1; Northwest Corner Section 6, T50N, R31W; No subsequent record of this corner was found. B. Description of corner evidence found and/or method applied in restoring or reestabilishing corner: A-1; Northwest Corner Section 6, T50N, R31W; Found a 1 ¼" diameter iron pipe projecting 18" above ground in the vicinity of the corner. This monumen bears S75°E a distance of 17.23 feet from the proportioned position. This corner is not mentioned in the field notes of Norman Thompson, RLS #4348. Furthermore, there is no physical evidence of U.S. bearing tree remains from this monument. I considered the corner lost and reestabilished it at the proportioned position. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-1; Northwest Corner Section 6, T50N, R31W; Set a 1"(I.D.) x 36" galvanized iron pipe with a 2" aluminum cap stamped as to location projecting 16" above ground. Set 7" spike NE/side 9" Sugar Maple N45°E 29.26' MILESKI PROFESSIONAL Set 7" spike NE/side 9" Sugar Maple N52°E 28.82' MILESKI PROFESSIONAL Set 7" spike NE/side 9" Sugar Maple N52°E 28.82' MILESKI PROFESSIONAL Set 7" spike NE/side 11" Sugar Maple N53°W 17.14' Location Post North 1.0' Location Post North 1.0' Location Post North 1.0' Location Post N						- j	54-	3	- 2 -	i
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this cardificate. A. Description of original monument and accessories and/or subsequent restoration: A-1; Northwest Corner Section 6, T50N, R31W; Originally established during U.S. Survey conducted by William Burt, D.S. in 1846 and monumented with an ironwood post witnessed by a Hemlock 30 S15°E 32 lks. and a Sugar 16 S70°W 7 lks. No subsequent record of this corner was found. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: A-1; Northwest Corner Section 6, T50N, R31W; Found a 1 ¼" diameter iron pipe projecting 18" above ground in the vicinity of the corner. This monumen bears S75°E a distance of 17.23 feet from the proportioned position. This corner is not mentioned in the field notes of Norman Thompson, RLS #4348. Furthermore, there is no physical evidence of U.S. bearing tree remains from this monument. I considered the corner lost and reestablished it at the proportioned position. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-1; Northwest Corner Section 6, T50N, R31W; Set a 1"(I.D.) x 36" galvanized iron pipe with a 2" aluminum cap stamped as to location projecting 16" above ground. Set 7" spike NW/side 11" Sugar Maple N45°E 29.26' MILESKI PROFESSIONAL SURVEYOR Set 7" spike SE/side 11" Sugar Maple S34°W 14.42' Northwest Corner Section 6, T50N, R31W; Set 7" spike SE/side 11" Sugar Maple N63°W 17.14' Location Post North 1.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes as well as a band around the tree at the upper blaze are painted red.	that under requirements of I above were in conformance survey instructions of the U decree of a Court of Law a conformance with the rules	P.A. 74, Michigan e with regulations nited States Depa and /or that the c of the Michigan E	P.A. of 1970, the constant rules therefore a rtment of the Interior, corner points mentione coard of Land Surveyor	ner points mentioned as required in the cu Bureau of Land Mana d in lines 3, 4 and 5 rs or by a Decree of	in lines 1 and 2 rrent manual of agement or by a bi above were in	5 6 -18	89	15-	11	—12— —13—
A. Description of original monument and accessories and/or subsequent restoration: A-1; Northwest Corner Section 6, T50N, R31W; Originally established during U.S. Survey conducted by William Burt, D.S. in 1846 and monumented with an ironwood post witnessed by a Hemlock 30 S15°E 32 lks. and a Sugar 16 S70°W 7 lks. No subsequent record of this corner was found. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: A-1; Northwest Corner Section 6, T50N, R31W; Found a 1 ¼ " diameter iron pipe projecting 18" above ground in the vicinity of the corner. This monumen bears S75°E a distance of 17.23 feet from the proportioned position. This corner is not mentioned in the field notes of Norman Thompson, RLS #4348. Furthermore, there is no physical evidence of U.S. bearing tree remains from this monument. I considered the corner lost and reestablished it at the proportioned position. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-1; Northwest Corner Section 6, T50N, R31W; Set a 1"(I.D.) x 36" galvanized iron pipe with a 2" aluminum cap stamped as to location projecting 16" above ground. Set 7" spike NW/side 11" Sugar Maple N45°E 29.26' MICHAEL D. MILESKI PROFESSIONAL SURVEYOR Set 7" spike NE/side 9" Sugar Maple S52°E 28.62' Set 7" spike NE/side 9" Sugar Maple S34°W 14.42' Northwest Corner Section 6, T50N, R31W; All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes as well as a band around the tree at the upper blaze are painted red.	NOTE: Not more than 2 corners, all in the same town and range, may be recorded						2021	22	_23	24
A. Description of original monument and accessories and/or subsequent restoration: A-1; Northwest Corner Section 6, T50N, R31W; Originally established during U.S. Survey conducted by William Burt, D.S. in 1846 and monumented with an ironwood post witnessed by a Hemlock 30 S15°E 32 lks. and a Sugar 16 S70°W 7 lks. No subsequent record of this corner was found. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: A-1; Northwest Corner Section 6, T50N, R31W; Found a 1 ¼ " diameter iron pipe projecting 18" above ground in the vicinity of the corner. This monumen bears S75°E a distance of 17.23 feet from the proportioned position. This corner is not mentioned in the field notes of Norman Thompson, RLS #4348. Furthermore, there is no physical evidence of U.S. bearing tree remains from this monument. I considered the corner lost and reestablished it at the proportioned position. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-1; Northwest Corner Section 6, T50N, R31W; Set a 1"(I.D.) x 36" galvanized iron pipe with a 2" aluminum cap stamped as to location projecting 16" above ground. Set 7" spike NE/side 9" Sugar Maple N45°E 29.26' MILESKI POF MICKIGAL PROFESSIONAL SURVEYOR No. 30091 No. 30091 All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes as well as a band around the tree at the upper blaze are painted red.	on this certificate	•				-	29 28-	27	-25	-25
A. Description of original monument and accessories and/or subsequent restoration: A-1; Northwest Corner Section 6, T50N, R31W; Originally established during U.S. Survey conducted by William Burt, Hemlock 30 S15°E 32 lks. and a Sugar 16 S70°W 7 lks. No subsequent record of this corner was found. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: A-1; Northwest Corner Section 6, T50N, R31W; Found a 1 ¼" diameter iron pipe projecting 18" above ground in the vicinity of the corner. This monumen bears S75°E a distance of 17.23 feet from the proportioned position. This corner is not mentioned in the field notes of Norman Thompson, RLS #4348. Furthermore, there is no physical evidence of U.S. bearing tree remains from this monument. I considered the corner lost and reestablished it at the proportioned position. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-1; Northwest Corner Section 6, T50N, R31W; Set a 1"(I.D.) x 36" galvanized iron pipe with a 2" aluminum cap stamped as to location projecting 16" above ground. Set 7" spike NW/side 11" Sugar Maple N45°E 29.26' Set 28.62' Suger Maple S52°E 28.62' Suger Maple S62°E 28.62' Suger Maple N63°W 11.42' Suger Section Post North 1.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes as well as a band around the tree at the upper blaze are painted red.										
Originally established during U.S. Survey conducted by William Burt, D.S. in 1846 and monumented with an ironwood post witnessed by a Hemlock 30 S15°E 32 lks. and a Sugar 16 S70°W 7 lks. No subsequent record of this corner was found. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: A-1; Northwest Corner Section 6, T50N, R31W; Found a 1¼" diameter iron pipe projecting 18" above ground in the vicinity of the corner. This monumen bears S75°E a distance of 17.23 feet from the proportioned position. This corner is not mentioned in the field notes of Norman Thompson, RLS #4348. Furthermore, there is no physical evidence of U.S. bearing tree remains from this monument. I considered the corner lost and reestablished it at the proportioned position. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-1; Northwest Corner Section 6, T50N, R31W; Set a 1"(I.D.) x 36" galvanized iron pipe with a 2" aluminum cap stamped as to location projecting 16" above ground. Set 7" spike NW/side 11" Sugar Maple N45°E 29.26' Set 7" spike NE/side 9" Sugar Maple S52°E 28.62' Set 7" spike SE/side 11" Sugar Maple S34°W 14.42' Set 7" spike SE/side 11" Sugar Maple S34°W 14.42' Set 7" spike SE/side 11" Sugar Maple N63°W 17.14' Location Post North 1.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes as well as a band around the tree at the upper blaze are painted red.	A. Description of origina	al monument an	d accessories and/o	or subsequent resto	oration:		32 33	34	35	_3 ₆ _
Originally established during U.S. Survey conducted by William Burt, D.S. in 1846 and monumented with an ironwood post witnessed by a Hemlock 30 S15°E 32 lks. and a Sugar 16 S70°W 7 lks. No subsequent record of this corner was found. 8. Description of corner evidence found and/or method applied in restoring or reestablishing corner: A-1; Northwest Corner Section 6, T50N, R31W; Found a 1%" diameter iron pipe projecting 18" above ground in the vicinity of the corner. This monumen bears S75°E a distance of 17.23 feet from the proportioned position. This corner is not mentioned in the field notes of Norman Thompson, RLS #4348. Furthermore, there is no physical evidence of U.S. bearing tree remains from this monument. I considered the corner lost and reestablished it at the proportioned position. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-1; Northwest Corner Section 6, T50N, R31W; Set a 1"(I.D.) x 36" galvanized iron pipe with a 2" aluminum cap stamped as to location projecting 16" above ground. Set 7" spike NW/side 11" Sugar Maple N45°E 29.26' Set 7" spike SE/side 9" Sugar Maple S52°E 28.62' Set 7" spike SE/side 11" Sugar Maple N63°W 17.14' Set 7" spike SE/side 11" Sugar Maple N63°W 17.14' Location Post North 1.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes as well as a band around the tree at the upper blaze are painted red.	A-1: Northwest Corr	ner Section 6	. T50N. R31W:			13				
A-1; Northwest Corner Section 6, T50N, R31W; Found a 1½" diameter iron pipe projecting 18" above ground in the vicinity of the corner. This monumen bears S75°E a distance of 17.23 feet from the proportioned position. This corner is not mentioned in the field notes of Norman Thompson, RLS #4348. Furthermore, there is no physical evidence of U.S. bearing tree remains from this monument. I considered the corner lost and reestablished it at the proportioned position. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-1; Northwest Corner Section 6, T50N, R31W; Set a 1"(I.D.) x 36" galvanized iron pipe with a 2" aluminum cap stamped as to location projecting 16" above ground. Set 7" spike NW/side 11" Sugar Maple N45°E 29.26' Set 7" spike NE/side 9" Sugar Maple S52°E 28.62' Set 7" spike NE/side 9" Sugar Maple S34°W 14.42' Set 7" spike SW/side 7" Sugar Maple N63°W 17.14' Location Post North 1.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes as well as a band around the tree at the upper blaze are painted red.	D.S. in 1846 at Hemlock 30	nd monumen S15°E	ted with an iron 32 lks. and a	wood post witr Sugar 16	nessed by a	' lks.	Barag.	a County		P
Found a 1 %" diameter iron pipe projecting 18" above ground in the vicinity of the corner. This monumen bears \$75°E a distance of 17.23 feet from the proportioned position. This corner is not mentioned in the field notes of Norman Thompson, RLS #4348. Furthermore, there is no physical evidence of U.S. bearing tree remains from this monument. I considered the corner lost and reestablished it at the proportioned position. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-1; Northwest Corner Section 6, T50N, R31W; Set a 1"(I.D.) x 36" galvanized iron pipe with a 2" aluminum cap stamped as to location projecting 16" above ground. Set 7" spike NW/side 11" Sugar Maple N45°E 29.26' MICHAEL D. MILESKI PROFESSIONAL SET 7" spike SE/side 11" Sugar Maple S52°E 28.62' PROFESSIONAL SURVEYOR SET 7" spike SE/side 11" Sugar Maple N63°W 17.14' No. 39091 SURVEYOR SOLUTION SET SUBJECT NO. 39091 SURVEYOR SOLUTION SET SUBJECT NO. 39091 SURVEYOR SOLUTION SET SUBJECT NO. 39091 SURVEYOR NO. 39091 SURVEYOR SOLUTION SET SUBJECT NO. 39091 SURVEYOR SOLUTION SURV	B. Description of corne	er evidence foun	d and/or method ap	plied in restoring o	or reestablishing	corner:				
bears S75°E a distance of 17.23 feet from the proportioned position. This corner is not mentioned in the field notes of Norman Thompson, RLS #4348. Furthermore, there is no physical evidence of U.S. bearing tree remains from this monument. I considered the corner lost and reestablished it at the proportioned position. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-1; Northwest Corner Section 6, T50N, R31W; Set a 1"(I.D.) x 36" galvanized iron pipe with a 2" aluminum cap stamped as to location projecting 16" above ground. Set 7" spike NW/side 11" Sugar Maple N45°E 29.26' Set 7" spike NE/side 9" Sugar Maple S52°E 28.62' Set 7" spike SE/side 11" Sugar Maple S34°W 14.42' Set 7" spike SW/side 7" Sugar Maple N63°W 17.14' Location Post North 1.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes as well as a band around the tree at the upper blaze are painted red.	A-1; Northwest Corr	ner Section 6	, T50N, R31W;							
A-1; Northwest Corner Section 6, T50N, R31W; Set a 1"(I.D.) x 36" galvanized iron pipe with a 2" aluminum cap stamped as to location projecting 16" above ground. Set 7" spike NW/side 11" Sugar Maple N45°E 29.26' Set 7" spike NE/side 9" Sugar Maple S52°E 28.62' Set 7" spike SE/side 11" Sugar Maple S34°W 14.42' Set 7" spike SW/side 7" Sugar Maple N63°W 17.14' Location Post North 1.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes as well as a band around the tree at the upper blaze are painted red.	bears S75°E a field notes of N bearing tree ren	distance of 1 orman Thom nains from th	7.23 feet from pson, RLS #434	the proportione 8. Furthermor	d position. T	This corne physical	r is not me evidence o	ntioned f U.S.		
Set a 1"(I.D.) x 36" galvanized iron pipe with a 2" aluminum cap stamped as to location projecting 16" above ground. Set 7" spike NW/side 11" Sugar Maple N45°E 29.26' Set 7" spike NE/side 9" Sugar Maple S52°E 28.62' Set 7" spike SE/side 11" Sugar Maple S34°W 14.42' Set 7" spike SW/side 7" Sugar Maple N63°W 17.14' Location Post North 1.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes as well as a band around the tree at the upper blaze are painted red.	C. Description of monu	ment for corner	and accessories es	tablished to perpe	tuate locating th	ne position o	f the corner:			
Set 7" spike NW/side 11" Sugar Maple N45°E 29.26' Set 7" spike NE/side 9" Sugar Maple S52°E 28.62' Set 7" spike SE/side 11" Sugar Maple S34°W 14.42' Set 7" spike SW/side 7" Sugar Maple N63°W 17.14' Location Post North 1.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes as well as a band around the tree at the upper blaze are painted red.	A-1; Northwest Corr	ner Section 6	, T50N, R31W;							
Set 7" spike NE/side 9" Sugar Maple S52°E 28.62' Set 7" spike SE/side 11" Sugar Maple S34°W 14.42' Set 7" spike SW/side 7" Sugar Maple N63°W 17.14' Location Post North 1.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes as well as a band around the tree at the upper blaze are painted red.		_	• •		m cap		AKE OF	MICHIGA		
All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes as well as a band around the tree at the upper blaze are painted red.	Set 7" spike Set 7" spike	NE/side SE/side	9" Sugar Ma _l 11" Sugar M 7" Sugar Ma _l	ple S52°E aple S34°V ole N63°V	28.6 V 14.4 V 17.1	2' -2'	PROFES SURV N N 39	SIONAL EYOR	TWEYOR *	
* This corner is also M-1 of T50N, R32W.	The lower blaze	is scribed "l	NBT". Both blaz				POFE	SSIONAL		
	* This corner is	also M-1 of	T50N, R32W.							

LIBER 4 PAGE 713

SUHVEY & REMONUMENTATION MAY 0 5 1997 COMMISSION