## SURVEY & REMONUMENTATION

APR 2 6 1995

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	OMMOON	Filing Requ	irement of Act 74, Mich.	P.A. 1970	
For corners in Baraga			<u> </u>	RECEIVED FOR I	RECORD THIS 19TH DAY
	ounty)	Located In:	Corner Code ##		A.D. 1994 AT 9:00 A.M
Dublic Loc	and Countries	51N 31\ T R	H-13	AND RECORDED IN LIBER 4 OF LAND CORNER RECORDATION ON PAGES	
Public Lan	id Suivey	T R		513-514.	TITON ON TROES
		T R		41106	Willand .
Property C	`ootrolling	T R S T R		BARRICA COUNTY	REGISTER OF DEEDS
in Section				DAMAGE COOKIT	REGISTER OF PEEDS
Miscellane		S T R		Register of Dee	ds Stamp & File Number
Property in	ı Sec.	S T R			
Lot No	, Red	corded Plat		A B C	DEFGHIJKLM
Private Cla	ims				
				3	
Michael	Mileski		December 9	94	8101112
		in a field survey on	P.A. of 1970, the corner points me	ntioned 5	<del>┞┞</del> ╀╃┼┼┼┼┼┤
lines 1 and 2	above were in o	conformance with regulations	and rules therefore as require	d in the	1716151413
			partment of the Interior, Bureau rner points mentioned in lines 3,	4 and 5	20 -21 -22 -23 -24
pove were in co	onformance with	the rules of the Michigan Boa	rd of Land Surveyors or by a Dec re-monumented, recovered, fo	ree of a	20 - 2122 - 23 - 24
ourt of Law opressed below		established, monomented, i	e-monumented, recovered, to	10 30	29 28 27 26 25
		ners, all in the same town	and range, may be recorde	3 1 4	<del>┤╴</del> ┤╶ <del>╎</del> ╶┤╶┤
on thi	is certificate.			12 -31	3 <del>2                                    </del>
Descriptio	n of original mo	onument and accessories	and/or subsequent restoration		
H-13; §	South One-q	uarter Corner Section	34, T51N, R31W, on 5	5th Correction Line.	
	·				LATE OF MICHIGAN
(	See back of	form.		AND CORNER	STE OF MICHIGAN
				OF 1990 County	MICHAEL D. + MILESKI *
			24		
			12-9-9	4	PROFESSIONAL CONTROL OF SURVEYOR No.
					39091
Descriptio	n of corner evic	dence found and/or metho	d applied in restoring or ree	stablishing corner:	POFESSIONE
H-13: 5	South One-a	uarter Corner Section	34, T51N, R31W, on 5	5th Correction Line.	A STATE OF THE PARTY OF THE PAR
	-				
					earing trees the condition
			probable U.S. corner.	reet west of a 3 f	oot wide stream (U.S. =
•	20.70 1001,		production		
			•		
·					
Description	n of monument	for corner and accessorie	s established to perpetuate	locating the position of	the corner:
<b>⊔</b> _1 <b>2</b> ∙ (	South One-a	warter Corner Section	34, T51N, R31W, on !	5th Correction Line	
•	•		_		
				alvanized iron pipe	with 2" aluminum ca
ć	appropriately	stamped as to locati	OII.		
	Set 60d spik			S11°E 25.72	
	Set 60d spik			36.62	
	Set 60d spik Set 60d spik		•	N55°W 8.70 N09°W 21.75	
	•				
			s marked with upper an		and scribed "NBT".
gned by	Coward		Date _		
urvevor's Mic	higan License I	No39091		COM APPROVER BY MICHIGAN ST	ATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

A. Description of original monument and accessories and/or subsequent restoration:

H-13; South One-quarter Corner Section 34, T51N, R31W, on 5th Correction Line.

Originally established during U.S. Survey conducted by Austin Burt, D.S. in 1845 and monumented with a wood post witnessed by a

Birch 5 N58°E 31 lks. (Inclusive) and a Birch 4 N55°W 39 lks. (Inclusive)

The late Norman Thompson, RLS #4348 states in his field notes dated 2 December 1943 (copies of which were obtained from Northern Hardwoods' office in L'Anse) that he set a hemlock post according to two yellow birch stumps in all probability neither having any conclusive marks. This conclusion is based upon Mr. Thompson placing a question mark along side the U.S. bearing tree entries in his transcription of the U.S. field notes. Mr. Thompson noted the following new bearing trees:

Hemlock 10 N51°E 20.0' (Presently alive and 16" in dia. having healed upper and lower face blazes Set 60d spike NW/side N49°E 20.00')

and a

Sugar 6 N72°W 21.7' (Recovered as a 36" tall solid stump 10" in dia. having healed upper and lower face blazes.)