

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 51N R 32W	F1
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S 4 T 51N R 32W	1
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 1 08/16/2011 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F1) Quarter corner on the north side of Section 4. 1986 - Monumented by Stephen D. Douglas, U.S.
Cadastral Surveyor, in a dependent resurvey of this township for the Bureau of Land Management. Set
5/8"x72" capped alum. rod. Tamarack 4" S02E 26 links, Tamarack 4" S48W 38 links.

(1-Sec. 4) West 1/16 corner on the north line of Section 4. 1986 - Established by Stephen D.
Douglas, U.S. Cadastral Surveyor, for the Bureau of Land Management, midway between corners E1 and
F1. Set 5/8"x108" long alum. post with BLM cap. Tamarack 4" S05W 92 links, Tamarack 4" S36W 50.5
links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F1) Found the 1986 5/8" capped alum. rod, in good condition, appropriately stamped, and at
substantial record bearing and distance from the witnesses of record. Accepted same as a careful and
faithful determination of the position of the corner.

(1-Sec. 4) Found the 1986 monument in good condition, at the record position, and at record bearing
and distance from the 1986 accessories. Accepted same as a careful and faithful establishment of the
position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F1) Found 5/8" dia. alum. rod with BLM cap.
Set measuring nail with MDNR tag in the side of:
4" Tamarack S53W 23.75' old blazes (1986 BT)
4" Tamarack S15W 16.85' do do
3" Cedar N02E 7.75' mrkd "1/4S NBT"
4" Tamarack S56E 12.0' do do
Set sq'd Tamarack post adjacent.
Bearings are magnetic.

(1) Fd. 5/8" dia. alum. rod with BLM cap
Set measuring nail with MDNR tag in the side of:
4" Tamarack S09W 60.8' fd. scribed "X BT"
3" Tamarack S39W 33.15' do do
3" Cedar S23E 80.4' mrkd "1/16S BT"
3" Tamarack S02E 88.65' do do
Set sq'd Tamarack post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 01/25/2012

For the Michigan Department of Natural Resources, Forest Management Division

