

MAY 0 5 1997

LAND CORNER RECORDATION CERTIFICATE

For corners in ' CO	MMISSION Filing	g Requirement of Act 7	'4, Mich. P.A. 1	970										
Baraga (County)	Baraga Located In: Corner Code #							RECEIVED FOR RECORD THIS 20TH DAY OF DECEMBER, 1996 AT 10:30 A.M. AND RECORDED IN LIBER 4						
1. Public Land Survey					ECORD 726-									
Property Controlling in Section Miscellaneous Property in Sec.	TR_ S TR_ S TR_			BARA			Y RE	GISTE	R OF	DE Numi	EDS ber			
4. Lot No , Re	corded Plat		_		B 6		- F	c u	т.т	v	T W			
5. Private Claims				1 A	<u>в</u> С	ו ע		n	ΪΪ		T M			
				2	6	— <u>5</u> —	4 —	—— <u>3</u> —	2	_	1 —			
ı, Michael Mileski	_, in a field survey on	November, 19	96 do hereby	3	1			+			+			
state that under requirements and 2 above were in conforma	of P.A. 74, Michigan P.A.	of 1970, the corner points mules therefore as required in t	entioned in lines 1 the current manual	4	7	— 8	9 	10-	-11		12			
of survey instructions of the Ur	nited States Department of	the Interior, Bureau of Land	Management or by		<u> </u>			 	1		+-			
a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law;					18	—17 	16-	15	14	e ! '	13-			
established, re-established, mo	numented, recovered, four	nd as expressed below:		7	1-1									
NOTE: Not more than 2 corr	ners, all in the same town	and range, may be recorded		8	19	20 	—21— 	22 	23		24—			
on this certificate.		-		9							1			
				10	30	29 	28 	 27-	26		25			
				11				 						
A. Description of original	monument and accesso	ries and/or subsequent re	storation:	12	31	32	33	34			36			
E-12; One-quarter Cor	ner common to Sec	ctions 32 and 33, T5	1N, R33W;			APP	PA:) LANI 345 OF	1990	NER				
See back of forn	ı.					./	Bar	aga Co	unty					
B. Description of corner e	evidence found and/or r	nethod applied in restorin	g or reestablishin	g corner:		12	18	-96			-			
E-12; One-quarter Cor	ner common to Sec	ctions 32 and 33, T5	1N, R33W;											
1 3/4" iron pipe intersection. Re	20 inches below the placed the copper in	plastic cap stamped ne road surface. Cor rod with a 1"(I.D.) x ridence of the positio	ner falls in the 18" galvanize	e center d iron p	of a	four	-way		over	а				
C. Description of monum	ent for corner and acce	ssories established to per	petuate locating	the posit	ion of	the c	orner:							
E-12; One-quarter Cor	ner common to Sec	ctions 32 and 33, T5	1N, R33W;											
Set a 1"(I.D.) x of an existing r	_	on pipe with a 2" alu	minum cap ins	side				TE OF	Mic	HIGH	Marke.			
i) Set 7" spike	e NW/side	11" Sugar Maple	N47°E	98.	82'	1	[*/	MICH	HAEL	D. 🦹	\ * ¶			
ii) Set 7" spik	e SW/side	4" Red Maple	S64°E		81'	. 1	*	•	LESK		\ *			
iií) Set 7" spik		10" Red Maple	S49°E		9.73°	•	5	SUR	VEYO	R	10			
iv) Set 7" spik		8" Red Maple	\$38°E \$15°W		5.76' 3.40'	7	LICENSEZ	<u>.</u> 2	No. 9091		WP/EYOR			
v) Set 7" spik vi) Set 7" spik		Power Pole Power Pole	515°W 574°W		3.40 3.06		100			es es	5			
vii) Set 7 spik		Power Pole	N35°W		25'		7	PROFE	5510	477	P			

(i) and (ii) are MDOT new bearing trees and are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes as well as a band around the tree at the upper blaze were painted red.

- (iii) is marked in the same manner as (i) and (ii).
- (iv) is not marked.
- (v) and (vii) are marked with a vertical red paint stripe.

(vi) is an MDOT accessory and is marked with a vertical red paint stripe.

Surveyor's Michigan License No. 39091

A. Description of original monument and accessories and/or subsequent restoration:

E-12; One-quarter Corner common to Sections 32 and 33, T51N, R33W;

Originally established during U.S. Survey conducted by Harvey Mellen, D.S. in 1845 and monumented with a hemlock post witnessed by a

Sugar 10 S82°W 12 lks. Hemlock 24 N38°E 12 lks.

This corner was recovered in 1981 by Brian Taavola, PS #21583. Mr. Taavola found this corner to be monumented with a "½" Iron pipe 1.5 feet south of Lindblom Road and on line with North-South fence.". The following accessories were established:

4" Maple N25°W 49.59'
7" Spruce N25°E 41.75'
Power Pole S05°W 30.17'
11" Maple S50°E 44.18'

Mr. Taavola remonumented the corner with a $\frac{1}{2}$ " rod with a $1\frac{1}{2}$ " brass cap placed in a monument box. Refer to LCRC prepared by Mr. Taavola and recorded in Liber 4 on page 15 of Baraga County Land Corner Records.

In 1991 Mr. Taavola re-recorded this corner indicating that "Corner was witnessed before the beginning of the road construction project and later reset from the wits with a 5/8" copper clad rod with a yellow plastic cap stamped MDOT 21583 in a monument box.". The following witnesses were noted:

 S75°W
 102.99'
 Power Pole

 S62°E
 88.87'
 4" Maple

 S35°E
 116.68'
 8" Maple

 N50°E
 98.85'
 10" Maple

Refer to LCRC prepared by Mr. Taavola and recorded in Liber 4 on page 226 of Baraga County Land Corner Records.

SURVEY & REMONUMENTATION

MAY 0 5 1997

COMMISSION