LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For	corners	in
-----	---------	----

For corners in										
Baraga (County)	_ Located In:	Corner Code #								
1. Public Land Survey	T 52N R 30W	C12								
2. Property Controlling in Section	S 32 T 52N R 30W S T R	8								
3. Miscellaneous Property in Sec.	S T R S T R S T R R									
4. Lot No. Rec	corded Plat		Regi	ster of	Deeds	Stamp	& File	Numb	er	
5. Private Claims			A B	C D	E	F G	н :	IJ	к	L M
			2 - 6-	<u> </u>			 - 3			
ı, Stephan J. Szyszkoski , in	a field survey on	/25/13 do hereby state	3	1			<u> </u>			
that under requirements of P.A.	74, Michigan P.A. of 1970, the corner	/25/13 do hereby state	4 - 7-			9	-10			ŢŢ
above were in conformance with re	regulations and rules therefore as require	ed in the current manual of support	5	44			Ĺ			
instructions of the United States D	Department of the Interior, Bureau of La	and Management or by a decree of	6	<u> </u>					П	\Box
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7									13-	
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law established of					Щ.		7			
re-established, monumented, recove	ered, found as expressed below:		9	Ī				23- 	100	24
			10-30-				+			+
NOTE: Not more than 2 corne	ers, all in the same town and range,	may be recorded	1 1	1 1	,	28	-27	26-	+	25-
on this certificate.			14			 	+-			┼┤
			12 31-	46 32	`——`	13-1-	34	—3 ⁵ 5—	+-	36
A. Description of original mo	onument and accessories and/or s	subsequent restoration:	13			<u> </u>			-	ليا
d.	corner, Section 32. Not									
The second second	common to Sections 31 and portionate measurement to with 4" alum. cap. 11")	The original regord b		~						ı i

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(8-Sec. 32) Established the position for the corner on a straight line between Quarter corner 1318.78' west and Center of Section 32 1318.78' east.

(C12) Found the 1965 monument in good condition and at record bearing and distance from the 1965 witnesses. The Sugar N05°W is now dead and down. The Maple SW is in good condition with overgrown blazes. The monument is substantially at the record position and I accept same as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. (C12) Found 1"ID I.pipe with 4" MI Dept. of Conservation cap. Set measuring nail with MDNR Set measuring nail with MDNR tag in the side of: 7" Sugar S80°E 17.0' tag in the side of: mrkd "1/16S BT" Maple S57°W 11.1 12" 13" Hemlock S06°E 11.95' old blazes do (1965 NBT) 10" Sugar N89°W 27.6' 10" Sugar N70°E 13.5' mrkd "1/4S NBT" do 5" Sugar S43°W 7.6' 15" Cedar N08°W 18.6' do do 8" Sugar N05°W 24.8' Set sq'd cedar post adjacent. do Set sq'd cedar post adjacent. E= 7912702.791 N= 231327.583 E= 7912300.916 N= 231334.339

> Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Dat Coord. Ref.=NGS PID D08499: N= 221257.624 m. E= 7884435.168 m.

Signed by Surveyor's Michigan License No. / 33986

08/15/2013

For the Michigan Department of Natural Resources, Forest Resources Division

LAND FORM APPROVED BY MICHIGAN STATE BOARD LAND

STEPHAN J

SZYSZKOSKI