

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Baraga

(County)

Located In:

Corner Code #

1. Public Land Survey

T 53N R 31W

K13

T R

T R

T R

2. Property Controlling
in Section

S 35

T 53N R 31W

13

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Nov 28 2001

I, Stephan J. Szyszkoski, in a field survey on _____, 20____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

(K13) Corner common to Sections 35-36 T53N-R31W and Sections 1-2 T52N-R31W. Corner remonumented in the original position by Dean C. DeLaMater RLS in 1953. Recorded in Liber 2 of LCRC, Page 204, Baraga Co. Records. 1" pipe with 4" brass cap. 9" Cedar N70E 43 links, 9" Hemlock S78W 21 links. The original 1846 survey notes show BTs for this corner: Cedar 12 N48W 46, Y.Birch 15 N34E 12, Fir 8 S49W 29, Hemlock 11 S65E 31.

(13-Sec. 35) Southeast 1/16 corner, Section 35. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(K13) Recovered the 1953 monument, a 1" ID iron pipe with 4" brass MI Dept. of Conservation tablet, in good condition and at record bearing and distance from the down and rotting remains of the 1953 accessories. The following original BTs were also recovered at record bearing and distance: Hemlock 11 rotted remains no markings visible, Y.Birch 15 rotted remains no markings visible, Cedar 12 stump remains meas. notch visible. Accepted the monument as a careful and faithful perpetuation of the position of the original corner.

(13-Sec. 35) Established the corner at the intersection of 1/16 lines situated as follows: The East 1/16 line of Section 35 at average bearing of the N-S 1/4 line and the East line of Section 35; the South 1/16 line of Section 35 parallel to the South line of Section 35.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K13) Found 1" ID I.pipe with 4" brass

MDOC cap. Blazed and scribed:

12" Cedar N40W 13.1'

"S35 NBT"

12" Hemlock S48W 30.0'

"S2 NBT"

11" Cedar S71E 32.6'

"S1 NBT"

13" Y.Birch N86E 36.1'

"S36 NBT"

Two squared cedar posts adjacent.

Bearings are magnetic. Distances are to notch in lower blaze.

(13) Set 1" ID x 32" I.pipe with 4" alum.

MDOCR cap. Blazed and scribed:

14" Cedar N07E 35.6'

"1/16S BT"

8" W.Ash N55E 35.6'

do

11" Cedar S40E 22.2'

do

13" W.Ash N58W 37.5'

do

Set squared cedar post adjacent.

Bearings are magnetic. Distances are to notch in lower blaze.



Signed by

Stephan J. Szyszkoski

Date

3/19/02

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources - Office of Property Management

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
 REVISED MAY 14, 1975
 REVISED JAN. 1983
 REVISED OCT. 1995