

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Chippewa Co.

4 Corners

| FOR CORNERS OF--                                       | LOCATED IN--                            | CORNER CODE NUMBER |
|--|---|--------------------|
| 1. PUBLIC LAND SURVEY                                  | T. <u>42</u> N. <u>2</u> E.             | I-10, L-11, I-6    |
| 2. PROPERTY CONTROLLING IN SECTION                     | <u>14</u> , T. <u>42</u> N. <u>2</u> E. | 3-Sec. 14          |
| 3. MISCELLANEOUS PROPERTY IN SECTION                   | T. <u>      </u> N. <u>      </u> E.    |                    |
| 4. LOT NO. <u>      </u> , RECORDED PLAT <u>      </u> |   |                    |
| 5. PRIVATE CLAIMS <u>      </u>                        |   |                    |

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 10-4 & 7-13, 1979, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on       , 19      , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

1/4 corners set by John Mullett, D.S. in 1845. Bearings were:

I-10 1/4 cor. bet Sec's 26-27: Cedar 8, N63°E, 10 lks. & Tam. 8, S75°W, 11 lks.  
 L-11 1/4 cor. bet Sec's 25-36: Cedar 8, N31°W, 7 lks. & Birch 8, S33°E, 9 lks.  
 I-6 1/4 cor. bet Sec's 14-15: Sugar 10, N74°E, 8 lks. & Beech 6, S73°W, 8 lks.  
 3-Sec.14 North 1/16 Corner, on West side of Sec. 14.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I-10 Re-established corner midway and on line between two section corners.  
 L-11 Re-established corner midway and on line between two section corners.  
 I-6 Restored corner midway and on line between two section corners.  
 3-Sec.14 Set corner midway between Section Corner to North and 1/4 Corner to South.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed 1" pipe with 4" aluminium cap at all corners. New Bearings:

I-10 10" Cedar, N44°E, 26.5' & 10" Cedar, N72°W, 21.1' & 6" Cedar, S10°W, 17.1'.  
 L-11 6" W. Birch, N69°W, 27.4' & 6" W. Birch, S44°W, 23.8' & 8" Aspen, N24°E, 4.6'.  
 I-6 8" Soft Maple, N74°E, 13.5' & 8" Spruce, S29°E, 16.7' & 5" Spruce, N77°W, 4.3'.  
 3-Sec.14 R. Maple Chump, S39°W, 67.1' & 7" Spruce, S21°E, 85.0', corner placed in rut of E-W Road.

SIGNED BY Billy D. Buckler DATE 3-5-80

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY        DATE       

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY        DATE       

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.       

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971  
 REVISED MAY 14, 1978

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

