

SURVEY & REMONUMENTATION

SEP 18 1997

COMMISSION

Approved By Delta County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On July 23, 1997

Robert L. ...
acting Chairman

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

DELTA

(County)

Located In:

Corner Code #

- 1. Public Land Survey
T 41 N R 23 W 21 MC K/L-13 LT BANK
T 41 N R 23 W 22 MC K/L-13 RT BANK
T _____ R _____
T _____ R _____
- 2. Property Controlling in Section
S _____ T _____ R _____
S _____ T _____ R _____
- 3. Miscellaneous Property in Sec.
S _____ T _____ R _____
S _____ T _____ R _____
- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

28 July 1997

9:00 a.m.

8 226

William C. ...
Delta County, Mich. Reg. of Deeds

Register of Deeds Stamp & File Number

I, M.P. DAVIS, in a field survey on 27 MAY, 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
K/L-13 [MC LT BANK] JOHN BURT, D.S.-1845-WOOD POST (CEDAR 16"-N58°W-99 LINKS)
NO RECORD EVIDENCE OF CORNER RECOVERY AND/OR SUBSEQUENT CORNER RESTORATION

K/L-13 [MC RT BANK] JOHN BURT D.S.-1845-WOOD POST (HEMLOCK 12"-S51°E-07 LINKS)
NO RECORD EVIDENCE OF CORNER RECOVERY AND/OR SUBSEQUENT CORNER RESTORATION

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
K/L-13 [REF MON TO MC ON LT BANK] NO CORNER EVIDENCE FOUND. ESTABLISHED REFERENCE MONUMENT AT EDGE OF UPLAND VEGETATION & ON THE SOUTH LINE OF SECTION 36 T41N R23W

K/L-13 [REF MON TO MC ON RT BANK] NO CORNER EVIDENCE FOUND. ESTABLISHED REFERENCE MONUMENT AT EDGE OF UPLAND VEGETATION & ON THE SOUTH LINE OF SECTION 36 T41N R23W

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K/L-13 [LT BANK] SET A 5/8" X 16" REBAR W/A 3 1/4" ALUM CAP STAMPED TO ID THE CORNER POSITION.
MAPLE 05" Y.BEICH 6" SURVEY MONUMENT SIGN POST LT BANK ESCANABA RIVER (TOP OF BANK)
N05°E S80°E EAST WEST
39.36' 42.13' 2.88' (TO FACE) 6'

K/L-13 [RT BANK] SET A 5/8" X 16" REBAR W/A 3 1/4" ALUM CAP STAMPED TO ID THE CORNER POSITION.
CEDAR 5" MAPLE 9" "X" ON STONE SURVEY MONUMENT SIGN POST RT BANK ESCANABA RIVER (TCP OF BANK)
N50°W S32°W N05°W S60°E EAST
16.11' 37.10' 17.00' 1.86' (TO FACE) 7'

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC & DISTANCES ARE TO A NAIL IN THE CENTER OF THE OBJECT, UNLESS OTHERWISE NOTED.

Signed by M.P. Davis Date 7/23/97
Surveyor's Michigan License No. 16426

| | | | | | | | | | | | | |
|----|----|----|----|----|----|----|---|---|---|---|---|---|
| A | B | C | D | E | F | G | H | I | J | K | L | M |
| 2 | 6 | 5 | 4 | 3 | 2 | | | | | | | |
| 3 | | | | | | | | | | | | |
| 4 | 7 | 8 | 9 | 10 | 11 | 12 | | | | | | |
| 5 | | | | | | | | | | | | |
| 6 | 18 | 17 | 16 | 15 | 14 | 13 | | | | | | |
| 7 | | | | | | | | | | | | |
| 8 | 19 | 20 | 21 | 22 | 23 | 24 | | | | | | |
| 9 | | | | | | | | | | | | |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 | | | | | | |
| 11 | | | | | | | | | | | | |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 | | | | | | |
| 13 | | | | | | | | | | | | |

