

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

Dickinson

(County)

Located In:

Corner Code #

**1. Public Land Survey**

T41N R 28W 813

**2. Property Controlling in Section**

S T R

**3. Miscellaneous**

S T R

Property in Sec.

S T R

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

Feb 15 2000

I, Stephan J. Szyszkoski, in a field survey on \_\_\_\_\_, 19\_\_\_\_ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

**A. Description of original monument and accessories and/or subsequent restoration:**

(B13) Standard Quarter corner on the 4th Correction Line on the South side of Section 31. Established in the original survey in 1846: "West on South side of Sec. 31... 40.00 Set Cedar Post qr. Sec. Corner. Birch 14 N63E 19, do 14 N18W 43. ... 82.00 corner of township". Found no subsequent record.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

(B13) The original post and accessories were not recovered. Reestablished the corner by single proportionate measurement to the original record, on the 4th Correction Line, between monumented standard corner 2636.26' east and monumented township corner 2768.03' west.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

(B13) Set 1" ID iron pipe with 4" aluminum MDNR cap. Blazed and scribed:  
 12" dbl Spruce N65E 62.2' "1/4S NBT"  
 9" dbl Spruce S27E 28.0' do  
 5" Ash S62W 38.8' "1/16S BT"  
 6" Ash N11E 61.8' do  
 DNR monument at corner #1, Sec.2,  
 T40N-R29W bears N87W 16.52' distant.  
 Bearings are magnetic. Distances to notch in lower blaze.



Signed by Stephan J. Szyszkoski  
 Surveyor's Michigan License No. 33986

Date 1/16/01

For the Michigan Department of Natural Resources - Forest Management Division