LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #							
(County)	_								
NORWAY TOWNSHIP									
1. Public Land Survey	T 41N R 29W	F06							
	TR								
	TR		1						
2. Property Controlling	STR								
in Section	S 12 T 41N R 29W	09							
S 440 43	STR		1						
3. Miscellaneous	STR								
Property in Sec.	STR								
4. Lot No. Bed	corded Plat		Heg	ister of	Deeds S	tamp &	& File	Numb	er
5. Private Claims			A B	C D	E F	G H	I	JΚ	LM
	7/31/201	340	2 6-	- s-		┸┪		-2	!
			3			<u> </u>	丄	_Ĭ}	
, Jeremy J. Pipp , ii	4 7-						120		
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2					Ti	Tì	\top		
above were in conformance with regulations and rules therefore as required in the current manual of survey								\Box	
nstructions of the United States Department of the Interior, Bureau of Land Management or by a decree of					-	15	}- -	-14	13
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with						1-1	\top		
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:				20		+-2 ² 2	<u>~</u> -	-23	-24-
e established, monuncined, recov	esed, found as expressed below.		9	- -	+				_
NOTE: Note: 2	and the state of t		1030-	29	28_	 2 ⁻	<u>-</u> -	-26	—25 —
NOTE: Not more than 2 corners, all in the same town and range, may be recorded					+-+	+			
on this certificate.				32_	3		4	-35	36
			13	\perp	1				
A. Description of original m	nonument and accessories and/or	subsequent restoration:							

- (F06) Center One-Quarter Corner of Section 16. Not set in original survey, no evidence of subsequent establishment.
- (09) Center-East One-Sixteenth corner of Section 12. Not set in original survey, Found 'T' Iron Fence Rail N19W 5.5 feet from calculated position, not of record.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (FO6) Corner position established at the intersection of the North-South and East-West One-Quarter lines of Section 16.
- (09) Corner position established mid-point and on-line between the Center One-Quarter corner and the East One-Quarter corner of Section 12. Found 'T' Iron not accepted.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F06)	DNR monument			(09)	DNR	R monument				
9" Poplar	N44E	19.03'	(1/4S,BT)	16" Cedar		N57E	15.66' (1/16S,BT)		
5" Spruce	\$70E	39.77'	(1/4S,BT)	10" Cedar		\$53E	24.28' (1/16S,BT)		
6" Spruce	S35W	26.05'	(1/4S,BT)	11" Cedar		S14W	30.36' (1/16S,BT)		
8" Poplar	N59W	24.85'	(1/4S,BT)	8" Cedar			3.79' (1/16S,BT)		
All trees are blazed, scribed, and				All tweet	All together blazed, scribed, and painted has been beautiful and painted to hail in					
painted. Measurements are to nail in										
side of tree, bearings are magnetic.			of tree	, B1	ar ing	s are magnetic.				
			(/ ,	The second second		2 + 8				

Surveyor's Michigan License No.

For the Michigan Department of Natural Resource

PROFESSIONAL SURVEYOR

PIPP

TATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Revised May 14, 1975

August 08, 2013

20258

Signed by

20261

Revised Jan., 1983 Rervised Oct., 1995