

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #
(County)		
NORWAY TOWNSHIP		
1. Public Land Survey	T 41N R 29W	I07
	T 41N R 29W	L05
	T R	
2. Property Controlling Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

_____ 2/19/2013AD
_____, Jeremy J. Pipp, in a field survey on 2/19/2013AD do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
(I07) Corner common to Sections 14, 15, 22, and 23. 1849: John Burt, DS. Set Cedar post witnessed by: Hemlock 14 N54E 38 links (25.08'); Hemlock 12 S15W 39 links (25.74'); 1959: Michigan DNR (Billy Buckler PS#8887) Set 1" pipe with 4" Brass cap witnessed by Cedar 8 N45W -, Cedar 8 S01E -. 1976: Michigan DNR (Arthur Enger PS#13581) found MDNR monument and witnessed : Cedar stump 12 S01E 17.9', Cedar 12 N38W 20.3', & Cedar 8 S01E 21.9' .

(L05) Quarter corner common to Sections 12 and 13. 1849: John Burt, DS. Set Sugar post witnessed by: Sugar 16 N67E 37 links (24.42'); Sugar 10 S57W 15 links (9.90'); 1959: Michigan DNR (Billy Buckler PS#8887) Set 1" pipe with 4" Brass cap witnessed by 11" Y. Birch S21E 28 links (18.48'), 10" Y. Birch N19W 60 links (39.60').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I07) Accepted found MDNR Monument and Two existing NBT Witnesses. Left MDNR monument in place and rewitnessed. Accepted found MDNR Monument and Witness remains as a careful and faithful REESTABLISHMENT of the position of the original corner.

(L05) Accepted found MDNR Monument and Two (one living & one stump) existing NBT Witnesses. Left MDNR monument in place and rewitnessed. Accepted found MDNR Monument and Witness remains as a careful and faithful REESTABLISHMENT of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I07)	DNR monument	(L05)	DNR monument
8" Cedar	N83E 13.63' (S14,NBT)	9" Maple	N71E 7.60' (1/4S,NBT)
EX 12" Cedar	S01W 22.23' (S22,NBT)	EX 17" Y. Birch	S20E 18.69' (1/4S,NBT)
9" B. Spruce	S55W 17.22' (S22,NBT)	4" Ironwood	S11W 13.27' (1/4S,NBT)
EX. 13" Cedar	N41W 20.73' (S15,NBT)	4" Maple	N24W 33.88' (1/4S,NBT)
All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic. A Carsonite rail was set North 1.5 feet.		All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic. A Carsonite rail was set North 1.5 feet.	

Signed by _____ Date July 22, 2013
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Forest Resources Division

20174

20173



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
Revised May 14, 1975
Revised Jan., 1983
Revised Oct., 1995