MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

RECEIVED

10 10 TO

FORESTAY DIV.
CONSTRVATION DEPT.

LAND CORNER RECORD

T 42 NR 27 W

| DESCRIPTION OF CORNER 1/4 corner between sections 31 and 36 DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap WITTNESSES TO CORNER Cedar 11" N 33 W 30 1/2 links Cedar 10" S 25 W 22 links | | | | Dickinson COUNT |
|--|-------------|----|--------|---------------------------------------|
| DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap WITTNESSES TO CORNER Cedar 11" N 33 W 30 1/2 links | DESCRIPTION | OF | CORNER | 1/4 corner between sections 31 and 36 |
| | DESCRIPTION | OF | CORNER | MONUMENT 1" pipe with 4" brass cap |
| Cedar 10" S 25 W 22 links | WIT TNESSES | то | CORNER | Cedar 11" N 33 W 30 1/2 links |
| | | | | Cedar 10" S 25 W 22 links |
| | | | | |
| | | | | |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed from original cedar bearing tree in fair condition. Found remains of tamarack stump at proper bearing and distance from corner to be other bearing tree.

Corner was found while cruising timber in this area.

Corner was placed and witnessed on 7 February 1956.

SURVEYOR'S SEAL

SIGNED Henry S. Peterson

DATE 2/8/56

REGISTERED LAND SURVEYOR