

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #
(County)		
Felch Township		
1. Public Land Survey	T 42N R 29W	K06
	T 42N R 29W	I04
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Jeremy J. Pipp, in a field survey on 8/02/2012AD do hereby state
8/07/2012AD
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(K06) Quarter corner common to Sections 13 and 14. 1849: John Burt, DS. Set Elm post
witnessed by Yellow Birch 22 S42E 19 links (12.54'), Sugar 18 West 25 links (16.50').

(I04) Quarter corner common to Sections 10 and 11. 1849: John Burt, DS. Set Post
witnessed by Cedar 10 S22W 22 links (14.52'), Cedar 12 N07E 27 links (17.82').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(K06) No evidence of original survey or subsequent restoration found. Corner position
reestablished by single proportionate measurement between the Southeast corner and the
Northeast corner of Section 14. Position is accepted as a careful and faithful
REESTABLISHMENT of the position of the original corner.

(I04) No evidence of original survey or subsequent restoration found. Corner position
reestablished by single proportionate measurement between the Southeast corner and the
Northeast corner of Section 10. Position is accepted as a careful and faithful
REESTABLISHMENT of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K06) DNR monument
8" Maple N72E 18.50' (1/4S,NBT)
9" Maple S28E 39.35' (1/4S,NBT)
7" Ironwood S32W 8.30' (1/4S,NBT)
4" Maple N25W 23.49' (1/4S,NBT)
All trees are blazed, scribed, painted,
and signed. Measurements are to nail in
side of tree, bearings are magnetic. A
carsonite rail was set North 1.5 feet.

Signed by Jeremy J. Pipp
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Office of Land and Fisheries

(I04) DNR monument
9" Ash S65E 42.18' (1/4S,NBT)
8" Ash S19W 42.92' (1/4S,NBT)
10" Ash N81W 33.11' (1/4S,NBT)
9" Ash N41W 46.72' (1/4S,NBT)

All trees are blazed, scribed, painted,
and signed. Measurements are to nail in
side of tree, bearings are magnetic. A
carsonite rail was set North 1.5 feet.

Signed by Jeremy J. Pipp Date August 28, 2012

PROFESSIONAL
SURVEYOR
No. 50447