

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

(DICKINSON COUNTY)

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. 43 N. R. 29 W.		#F-11
2. PROPERTY CONTROLLING IN SECTION 33, T. 43 N. R. 29 W.		#1
3. MISCELLANEOUS PROPERTY IN SECTION_____, T._____, S. R._____, E. W.		
4. LOT NO._____, RECORDED PLAT_____		
5. PRIVATE CLAIMS_____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 18, 1979, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on_____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner F-11 (1/4 corner between Sections 28 & 33, T43N, R29W):
 Willow post (Not found. No subsequent monuments found.)
 Spruce 10 N27W 13 (Not found. No subsequent accessories found.)
 Cedar 6 S25E 4 (Found. No subsequent accessories found.)

Corner 1 (West 1/16 corner between Sections 28 & 33, T43N, R29W):
 Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner F-11: Restored on line bet. Section Corners 39.900 ch. to E and to W. There is an original cedar BT stump bearing N30°50'W 30.4 ft. from corner as restored; unfortunately, it has been bull-dozed out from its original position during road construction, faces the wrong way, and it is not possible to determine where it originally stood. The lower witness blaze with scribe marks, though overgrown, is plain and doubtless authentic. Regretfully, I had to restore the corner by proportionate measurement.

Corner 1: Established on line between 1/4 cor. 19.950 ch. E and Sec. Cor. 19.950 ch. W.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner F-11: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
 Cedar 12 S57°E (mag.) 22.3 ft. "1/4S, NBT"
 Cedar 6 S72°W (mag.) 9.2 ft. "1/4S, NBT"
 Declination 2° 45' West.

Corner 1: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
 Sugar Maple 6 S30°E (mag.) 37.6 ft. "1/16S, BT"
 Sugar Maple 5 N11°W (mag.) 25.0 ft. "1/16S, BT"
 Declination 3° 35' West.

SIGNED BY_____ DATE_____

SURVEYOR'S MICHIGAN REGISTRATION NO._____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY_____ DATE_____

APPROVED AND SIGNED BY Arthur O. Enger DATE March 7, 1980
 CHIEF OF SURVEY PARTY
 MICHIGAN REGISTERED LAND SURVEYOR

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

