

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—	LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY <u>19</u> T. <u>44N</u> N. <u>27W</u> E. S., R. <u>W.</u>		A-9 Wit.
2. PROPERTY CONTROLLING IN SECTION _____, T. _____ N. S., R. _____ E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____ N. S., R. _____ E. W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, David Babbitt, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on January 15, 1985, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

A-9) Witness Corner. On the west section line of Section 19 - 300.0' northerly of the SW section corner of Section 19. This point not previously marked.

GLO record for the SW section corner, Section 19. Set cherry post in left bank of stream. Tam 16 North 3.83. Michigan Dept. of Conservation, March 12, 1952. 1" pipe with 4" brass cap. Set 83 Lks. north of where the section corner belongs. Bank erosion from river would place true corner in river. One original BT still in place, down but in good condition. NBT's 12" cedar N45W 223 Lks. 12" spruce N1E 305 Lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A-9) Set monument on the west section line 300.0' northerly of the SW section corner of Section 19 which now falls in the Escanaba River. Section corner position determined from the cedar NBT marked in 1952. The monument set in 1952 has apparently also washed into the river.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-9) DNR Monument.
13" cedar S60W 34.3'
15" cedar N67W 46.2'
15" cedar N33E 27.65'
6" spruce S5E 41.1'

SIGNED BY David B. Babbitt DATE 1-16-85

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)

FOR STATE AND UNITED STATES AGENCIES: