

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T 51N R 36W	C9
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S 19 T 51N R 35W	12
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

I, Stephan J. Szyszkoski, in a field survey on C9 04/21/2011
12 05/02/2011 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(C9) Corner common to Sections 19-20-29-30. 1974 - Reestablished by A.O.Enger RLS #13581 at a
position in accord with the physical locatino of existing roads and fencelines. Set 1"IDx24" I.pipe
with 3.5" aluminum cap buried in road. Power Pole S13W 32.97' to nail/washer, Power Pole N36W 78.08'
to nail/washer.

(12-Sec. 19) South 1/16 corner, Section 19. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C9) The 1974 monument was recovered, disturbed, bent over by a road grader, and at the intersection
of the existing physical centerlines of N.Laird and Ovist Roads. The 1974 witnesses are no longer
present though I note that the power poles currently in place, seemingly newer than 1974, are located
very near to the record bearing and distance but for the distances and bearings being transposed (see
below). Remonumented the 1974 position as best as could be determined from the position and attitude
of the existing monument and verified the location by measurement to corners north, east, and west.
Accepted the 1974 position as a careful and faithful reestablishment of the position of the original
corner.

(12-Sec. 19) Established the corner midway and on a straight line between Center of Section 1317.67'
North and Quarter corner 1317.67' South. From the position for the corner a fence corner with old
fencing running south and west is 39' West and 13' North.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C9) Set 1"IDx32" I.pipe with 4" alum. MDNR cap
buried to 9" below the graveled road surface.
Set measuring nail with MDNR tag in the side of:
6" Apple N61E 54.5' mrkd "S20 NBT"
7" Hemlock S45E 62.25' "S29 NBT"
Power Pole 5135 30E26 S17W 78.4'
Power Pole 5135 19R25 N36W 32.7'
Bearings are magnetic.

(12) Set 1"IDx32" I.pipe with plastic cap
stamped "MICH DNR PS 33986"
Set measuring nail with MDNR tag in the side of:
4" Maple N24E 8.65' mrkd "1/16S BT"
6" Balsam S25E 5.9' do
8" Maple S35W 7.9' do
4" Cherry N54W 13.7' do
Set sq'd cedar post/location poster adjacent.
Bearings are magnetic.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 06/02/2011

For the Michigan Department of Natural Resources, Office of Land and Facilities

