## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton	Located In:	Corner Code #												
(County)	_													
1. Public Land Survey	TR		.											
2. Property Controlling	S 13 T 52N R 35W	8	.											
in Section	S 14 T 52N R 35W S T R													
3. Miscellaneous	s		٠											
Property in Sec.	s r R		٠											
• •			٠	R	egiste	r of De	eds	Starr	3 qr	File	Nun	nber		
4. Lot No. , Re	corded Plat				n - a									_
5. Private Claims	7-		•	ĻĴ—		- B	<u> </u>	1 6	, ,			/ K		f
	8 (	08/09/2010	i	2	<b>∳</b> —	- 5-	╁╌	1	-	-				Į.
ı, Stephan J. Szyszkoski , in a field survey on 6 07/2		07/27/2010 do here	eby state	"			<b>†</b>							t
that under requirements of P.A.	74, Michigan P.A. of 1970, the cor	ner points mentioned in line	s 1 and 2			8	1	9	<u> </u>	٣	1	'	1	12
above were in conformance with regulations and rules therefore as required in the current manual of survey														t
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of						—17	<del> </del> 1	6—	-1	5	1	4	-61	

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

re-established, monumented, recovered, found as expressed below:

on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, g

(8-Sec. 13) West 1/16 corner, Section 13. Not established in the original survey. Found no subsequent record.

(6-Sec. 14) Northeast 1/16 corner, Section 14. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(8-Sec. 13) Found no monumentation at the corner position. There are old and unmaintained fences running north and east from near the corner position but judging from their courses (N5W and N81E), they appear to have been run in on approximate lines. They intersect at a point about 32.5' north of the position for the corner. Established the corner midway and on a straight line between Center of Section of record 1315.94' east and Quarter corner of record 1315.94' west.

(6-Sec. 14) Established the corner at the intersection of straight lines connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 8" twin Maple N10E 3.85' mrkd "1/16S BT" 8" Spruce N74E 20.45' do 5" Maple S48W 15.05' do 7" Spruce N83W 19.75' do Set sq'd Cedar post adjacent. Bearings are magnetic.

(6) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 11" Y.Birch N27E 28.15' mrkd "1/16S BT" 9" Maple N48E 36.05' do 4" W.Pine S12W 26.95' do 4" Spruce N44W 12.9' do

Set sq'd cedar post adjacent. Bearings are magnetic.

10

13

Signed by Surveyor's Michigan License No.

Surveyor's Michigan Department of Natural Resources and Environment, Forest Management

id Environment, Forest Wanagement Div

SZYSZKOSKI VisionLAND SURVEYOR

SURVEYOR

ESSIONAINOIVEYORS, AUST

d Oct., 1995

16520 16514