//

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	Filing Requirement of Act 74, Mich. P.A. 1970									
Moughton (County)	Located In:	Corner Code #								
1. Public Land Survey	T 52H R T 52H R T R	<u> 35W </u>								
Property Controlling in Section Miscellaneous Property in Sec.	S TR S TR S TR		Register of Deeds Stamp & File Number							
4. Lot No, Records			- ABCDEFGHIJKL							
[Stephan J. Szyszkoski	, in a field survey on	Nov 29 1995								

requirements of P.A. 74, Michigan P.A. or 1970, the corner points mentioned in lines 1 and 2 above were an conformance with regulations and rules therefore as required in the current manual of survey) instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Line and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1		\Box							[
2	 	<u>6</u> —	├ - :	\$	-	<u> </u>	⊢;	-	<u>-</u> :	ž		<u>i</u> —
3		L_							_			_
Ī	١.	<u>l</u>		ĺĺ		Ĺ				Į I		
4	Ε.	7	-		_	9—	_1	<u>-</u>	ı	1	1	
5		-		Н	Н	_		-	_	\vdash	-	_
6	L,		_,	Ĺ	_,	6	,	5	_,		1	.
	•	ĭ	Ĩ	ĺ	. i	Ĭ	וֹ וֹ	Ĭ		ı l		Ī
7		_				_						
θ	<u>_1</u>	9	2	O	—2	1	<u>2</u> 2	2—	—2	3	-2	4—
9												
-		l_ i	J		j					١. ا	إ	
10		io—	—²,	9-		8-	2		— Z	⁵⊟	~	
11	_	-	\vdash	\vdash		-		-	_	-	\vdash	
12	3	<u>ا</u> _ا	3	2_	3		_3	_	_3	5_		6—
		اً ا	ĬĬ	Ī	Ī	Ī	Ī	_		Ī	Ĭ	Ī.
13		ш.		ш	لببا				L .			

A. Description of original monument and accessories and/or subsequent restoration:

(Gil) Section Corner common to Sections 27-28-33-34. Corner reestablished in 1953 by Billy D. Buckler, RLS, by Double Proportionate Measurement. Buckler placed a 1° pipe with 4° brass cap at the corner and marked the following MBTs: 14° Hemlock, S74E 48 links, 12° W. Pine N72W 78 links.

(XII) Section corner common to Sections 25-26-35-36. Corner remonumented in 1953 by Billy D. Buckler, in the original position, as determined from one original B.T. Buckler placed a 1° pipe with 4° brass cap at the corner and marked the following new bearing trees: 14° Cedar M55E 45 links, 10° Hemlock S40E 56 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G11) Found the 1953 monument, a 1° I.D. iron pipe capped with a 4° dia. brass Michigan Dept. of Conservation tablet, in good condition, and at record bearing and distance from the 1953 accessories. The 1953 scribing is visible on the Hemłock, which is now dead, and the W. Pine was found as a cut stump. Left the monument in place, and marked 4 new witnesses as described below.

[K11] Recovered the 1953 monument, a 1° I.D. iron pipe capped with a 4° dia. brass Michigan Dept. of Conservation tablet, in good condition, and at record bearing and distance from the remaining Cedar NBT, in good condition. The 1953 Hemlock was not recovered. Left the monument in place and marked three new accessories as described below.

(G11) Found 1° pipe with 4° brass MI Dept. of Conservation tablet. Blazed and scribed the following new	[Kii] Found i pipe with Dept, of Conservation tal and scribed the followin	blet. Blazed	THE OF MICHIEF
bearing trees:	4° Sugar S62E 14.4'	"S36 NBT"	* STEPHAN J.
8" Hemlock S25E 17.9' "S34 NBT"	16" Hemlack \$38W 36.5'	"\$35 N87"	SZYSZKOSKI \
7" Y. Birch S43W 2.7' "S33 NBT"	-8" Y. Birch N45W 12.5"	"S26 NBT"	LAND
5' Sugar N42W 9.6' "S28 NBT"	Bearings are magnetic		SURVEYOR
8" Hemlock N56E 6.9' "S27 NBT"			33986
Bearings are magnetic.			33900
1.1.1			AND SU

Signed by Stephen Synglefish:
Surveyor's Michigan License No. 33986

Date 3/13/97

For the Michigan Department of Natural Resources - Forest Management Division