

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T 53N R 32W	MC E. of F1
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S 4 T 53N R 32W	F2
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No.	Recorded Plat	
5. Private Claims		

I, Stephan J. Szyszkoski, in a field survey on MC 04/25/2011
F2 04/26/2011 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(MC E. of F1) Meander corner on Lake Superior between Section 4 T53N-R32W and Section 33 T54N-R32W.
1845 - Established by Wm.A.Burt Deputy Surveyor 18.68 chains east of the Quarter corner. Set post.
W.Pine 10 N37W 5 links. Found no subsequent record.

(F2) Center of Section 4. 1978 - Restored by K.L.Sackett RLS #19006. Set 1"ID iron pipe with 4"
aluminum cap. 5" Cedar N15E 8.8', 7" Cedar West 56.8', 4" B.Ash S25E 4.9'. 2010 - the 1978 monument
was recovered by Jeffrey J. West PS #46697 in good condition but with the aluminum cap missing. Mr.
West used the monument to control the E-W 1/4 line and his establishment of a position for an
Auxiliary Meander Corner at the Lake Superior shore, 745.94' to the east.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(MC E. of F1) The original post and accessory have been washed away by the encroaching Lake Superior
and were not recovered. Found no evidence of the position of the original corner or subsequent
restoration on the ground. Reestablished the corner at record distance 18.68 chains (1232.88 ft.)
east of Quarter corner F1 on a prolongation of the Township Line between E1 and F1. The position for
the Meander Corner falls in the lake and was not monumented. Established a Witness Corner 19' west
of the 7' high bluff above the lake, 80.00' west of the reestablished corner position and on the
reestablished Township Line. Placed a monument at the Witness Corner position, as described below.

(F2) Found the 1978 monument, in good condition but with missing cap, projecting about 10" above
ground, and at record bearing and distance from the Cedar BT N15E, in good condition with overgrown
blazes. The position of the monument agrees well with other monumentation found along the 1/4 line
east and west. I accept the monument as a careful and faithful determination of the position of the
corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(MC) Set 1"IDx32" I.pipe with 4" alum. MDNR cap
80.00' West of the Meander Corner position.
Set measuring nail with MDNR tag in the side of:
11" Maple N10E 21.1' mrkd "WC BT"
5" Poplar S27E 11.05' do
5" Maple S34W 8.25' do
6" Balsam N22W 16.7' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

(F2) Found 1"ID I.pipe with stem of alum. cap.
Set measuring nail with MDNR tag in the side of:
8" Cedar N20E 9.4' old blazes 1978 BT
5" Y.Birch East 22.1' mrkd "C1/4 BT"
6" Y.Birch S46W 5.2' do
5" Y.Birch N46W 17.6' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5					3		2		1	
3													
4	7		8					10		11		12	
5													
6	18		17					15		14		13	
7													
8	19		20					22		23		24	
9													
10	30		29					27		26		25	
11													
12	31		32					34		35		36	
13													

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 06/20/2011

For the Michigan Department of Natural Resources, Forest Management Division

