LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #		
1. Public Land Survey	T 53N R 35W T R R 35W	J13 (GCDB 540100)		
2. Property Controlling in Section	S T R S T R	(GCDB 600140)		
3. Miscellaneous Property in Sec.	S T R			
4. Lot No. , Red 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number A B C D E F G H I J K L	
1, Stephan J. Szyszkoski, in a field survey on 09/29/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, monumented, recovered, found as expressed below:				
	ers, all in the same town and range	e, may be recorded	9 10 30 29 26 27 26 25 11 12 31 32 33 34 35 36	

A. Description of original monument and accessories and/or subsequent restoration:

(J13) Standard 1/4 corner on the South line of Section 35. 1845 - Established by W.A.Burt, Deputy, midway and on the Township line between Section corners 40.00 chains east and west. Set post. Tamarack 20" N58°E 33 links, B.Ash 6" N65°W 22 links. 1926 - Notes of P.A.Larson state [refering to N1/4 of Section 2 52-35] "B.T. Tam 18" stdg". Note, this is not a common 1/4 corner with Section 2, T52N-R35W.

(K12) Quarter corner common to Sections 35-36. 1846 - Established by S.W. Higgins, Deputy, midway and on the Section line between Section corners 40.00 chains north and south. Set post. Cedar 10" N21°W 11 links, Cedar 12" S05°E 6 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(J13) The original post and accessories were not recovered. The OBT Tamarack mentioned in the 1926 Larson notes was not recovered. There is, in the corner area, a rotted 28" Tamarack stump, no markings, but it is located too far west of the record position to suppose that it is the original BT, being about 13' west of the position subsequently monumented. Finding no evidence of the position of the original corner on the ground, I reestablished the position for the corner midway and on the Township line between Section corners 2642.41' east and west.

(K12) The original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. Recestablished the position for the corner midway and on the Section line between Section corners 2596.33 feet north and south. The position falls in a swamp.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J13) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 9" Cedar S76°W 22.65' mrkd "1/4S NBT" 8" Cedar N30°W 17.05' do 5" Cedar N22°E 6.1' do 10" Cedar S47°E 18.6' do Set sq'd cedar post adjacent. E= 7869752.211 N= 240968.083	(K12) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: Dead standing 19" Cedar S34°E 33.9' "1/4S NBT" 4" Balsam S27°W 36.0' do Brown Carsonite post North 1.0' Sq'd cedar post South 2.0' E= 7870590.837 N= 241741.080
---	--

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.

Coord. Ref.=NGS PID D08499: N= 221257.624 m. E= 7884435.169 m.

Signed by Lishus Causalia Date 11/04/2015
Surveyor's Michigan License No. 33986

inse No. U 33986

For the Michigan Department of Natural Resources, Forest Resources Division

FORM APPROVED BY MICHIGAN STATE BOARD

STEPHAN J.
SZYSZKOSKI
LAND
SURVEYOR
ROMESSIONAL ARBYTORS, JAN 25, 11
33980/isechana Ph. 19
AND SREVISIONEL, 199