## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton	Located In:	Corner Code #				
(County)						
1. Public Land Survey	T 53N R 35W	M13 (GCDB 700100)				
2. Property Controlling in Section	S T R S T R					
3. Miscellaneous Property in Sec.	S T R		Register of Deeds Stamp & File Number			
4. Lot No. Recorded Plat						
5. Private Claims			ABCDEFGHIJKL			
			2 - 6 - 5 - 1 - 3 - 2 - 1 -			
ı, Stephan J. Szyszkoski , ir		4 7 9 9 9 9				
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2						
above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6						
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7						
	d of Land Surveyors or by a Decree	, 8 19 20 21 22 23 24				
re-established, monumented, recove	ered, found as expressed below:		9			
MATP II .			10 30 29 28 27 26 25			
NOTE: Not more than 2 corn	11					
on this certificate.			12 31 32 33 34 35 36			
A Description of column 1			13			

A. Description of original monument and accessories and/or subsequent restoration:

(M13) Cor. to Twps. 53N-52N and 35W-34W. 1845-W.A.Burt, Deputy, set post. Sugar 12" S82°W 30 links, Sugar 20" N49°E 27 links. Notes of P.A.&M.C. Larsen while cruising timber: "1920 - Set post from roots of B.T.s & put stones at base. 1948-Found 1"I.P. & cedar post". 1966-B.D.Buckler RLS: This corner replaced as located by M.C. Larsen, Hancock, Mich. No original evidence remains. Corner lies in line with a good logging road to West. 1-1/4"x30" Iron Pipe. 22" Hemlock S84°E 8.9', 9" Soft Maple S04°E 27.0'. 2001 L4-P217 - S.C.Hein, PS, remonumented the corner position at record distance and angle from Fesing's 1920 notes [Fesing had traversed around and subdivided Section 31 T53N-R34W]. Set 3/4" capped pipe. 8" R.Maple N39°E 43.93', 20" Maple Snag S23°E 19.92', 8" R.Maple S59°W 51.24', 9" R.Maple N54°W 61.29', 1-1/4" pipe S27°27'03"E 16.36'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(M13) Found a 1-1/4" iron pipe (with 3/4" I.pipe adjacent) in the bank on the south side of a logging road, roughly at the PC of a curve to the right, concave SW'ly. This pipe is that noted in the L4-P217 LCRC. The top of the pipe has been bent but the underground portion is straight and plumb. The 1966 NBT Maple SO4°E 27.0', now a cut and rotted stump, is at record bearing and distance. The 1966 Hemlock is not present and would have been destroyed by road construction. 1/4 corner M12, monumented in 1966 by Buckler midway between section corners, falls 1.57' west and 0.98' north of the midpoint between M11 and this pipe. I accept the pipe as the best available evidence of the position of the original corner. I examined the Fesing notes of the survey of Section 31 T53N-R34W and I concluded that they contain an error because I could find no interpretation of them which would yield a mathematically closed figure around the perimeter of the section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(M13) Found 1-1/4" I.pipe, replaced with 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:

3" Oak N36°E 42.9' mrkd "S31 NBT"

3" Hemlock S20°W 2.85' w/ loc. tag "S1 NBT"

10" Oak S34°W 13.95' do

8" Y.Birch N01°W 59.7' "S36 NBT"

Set sq'd cedar post adjacent.

E= 7872177.865 N= 240916.768.



Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum. Coord. Ref.=NGS PID D08499: N= 221257.624 m. E= 7884435.169 m.

Signed by	tephan	Lynantica	lo ·	Date	11/04/2015
Surveyor's Michigan L	icense No.		33986		

Revised Oct., 1995