

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 35 T 42N R 32W	3
	S T R	(GCDB 500180)
	S 27 T 42N R 32W	2
	S T R	(GCDB 460300)
	S T R	
3. Miscellaneous Property in Sec.		
4. Lot No.	Recorded Plat	
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 04/16/14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(3-Sec. 35) North 1/16 corner between Sections 34 and 35. 1971 - Established by A.O.Enger RLS on the Section line between Section corner 20.050 ch. N and 1/4 corner 20.051 ch. S. Set 1"IDx36" I.pipe with 4" alum. cap. Tamarack 10" N11°E 87.2', W.Spruce 8" N25°W 79.1'

(2-Sec. 27) East 1/16 corner between Sections 22 and 27. 1971 - Established by A.O.Enger RLS on the Section line between Section corner 20.074 ch. E. and 1/4 corner 20.074 ch. W. Set 1"IDx36" I.pipe with 4" alum. cap. Red Maple 6" S26°E 42.0', W.Birch 11" S47°W 30.9'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(3-Sec. 35) Found the 1971 monument in good condition, substantially at the record position, and at record bearing and distance from the 1971 BTs: the Tamarack BT N11°E 87.2' is now standing dead with markings visible. The W.Spruce BT is in good condition. Accepted the monument as a careful and faithful establishment of the position of the corner.

(2-Sec. 27) Found the 1971 monument in good condition and substantially at the record position. The 1971 BTs were not recovered. Accepted the monument as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(3) Found 1"ID I.pipe with 4" alum. MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:  
11" W.Spruce N22°W 79.2' old blazes (1971 BT)  
8" Spruce N54°W 7.95' mrkd "1/16S BT"  
4" W.Pine N38°E 19.15' do  
3" double Sugar S07°E 17.5' do  
E= 7900571.125 N= 135659.253

(2) Found 1"ID I.pipe with 4" alum. MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:  
9" Maple N44°E 20.35' mrkd "1/16 S BT"  
14" Oak S74°E 47.4' do  
11" Oak in clump S24°E 42.15' do  
12" Oak S60°W 44.75' do  
Set sq'd cedar post adjacent.  
E=7900195.047 N= 137681.126

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)  
Coord. Ref.=NGS PID AA8081: N= 147176.690 m. E= 7895147.466 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 06/04/2014

For the Michigan Department of Natural Resources, Forest Resources Division

