## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For	cn	rne	rc	in
I UI	LU	HIC	1.5	111

on this certificate.

iron (County)	Located In:	Corner Code #			
1. Public Land Survey	ΤR	iii M	(5)	E.	
<ul><li>2. Property Controlling in Section</li><li>3. Miscellaneous Property in Sec.</li></ul>	T R S 1 T 43N R 36W S T R S 1 T 43N R 36W S T R S T R	14 (GCDB 700620) 9 (GCDB 660640)			
	corded Plat		Register of Deeds Stan	np & File Number	Т. М
97			2 6 5 5 4	3-2-	1
above were in conformance with instructions of the United States a Court of Law and /or that the	74, Michigan P.A. of 1970, the corner regulations and rules therefore as requir Department of the Interior, Bureau of L corner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree	red in the current manual of survey and Management or by a decree of 1.5 above were in conformance with	5 6 -18 -17 -16 -	-15 -14	-1213

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

 $(14-Sec.\ 1)$  South 1/16 corner between Section 1 T43N-R36W and Section 6 T43N-R35W. Not monumented in the original survey.

(9-Sec. 1) Center-East 1/16 corner, Section 1. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(14-Sec. 1) At a point N77°E 0.09' from the prescribed point for this position (midway and on the Section line between Section and 1/4 corners), I found a 1/2" dia. rebar, in good condition, previously set by an unknown surveyor, which I accepted as a careful and faithful establishment of the position of the corner.

(9-Sec. 1) Established the position for the corner midway and on a straight line between 1/4 corner 1309.91' east and the intersection of 1/4 lines of Section 1, 1309.91' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(14) Found 1/2" rebar with 3' tall metal fence post and bent 3/4" iron pipe adjacent. Set measuring nail with MDNR tag in the side of:

14" W.Pine S60°W 16.3' mrkd "1/16S BT"

9" W.Pine S87°W 19.4' do

4" Balsam N46°W 6.8' do

P.Pole #92-21597 40-5 N50°E 25.2'

E= 7865480.500 N= 153238.819

(9) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
8" Cedar N16°E 19.45' mrkd "1/16S BT"
11" Cedar S07°W 3.6' do
6" Cedar S50°W 20.3' do
6" Cedar N36°W 21.1' do
E= 7865091.392 N= 153647.604

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83 (2011) 1 Coord. Ref.=NGS PID DI0209: N= 145460.522 m. E= 7873677.972 m.  Signed by Date 02/05/2015	STEPHAN J. SZYSZKOSKI
Surveyor's Michigan License No. 0 33986	SURVEYOR

For the Michigan Department of Natural Resources, Forest Resources Division

Signal Buvergra, 111 . (2, 1971 Decimally 14, 1975 Revised Jan., 1983

Revised Oct., 1995

FORM APPROVED BY MICHIGAN STATE BOARD OF THE BIONAL