

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T 45N R 31W	A10 (GCDB 100240)
2. Property Controlling in Section	S 30 T 45N R 31W	B10 (GCDB 140240)
3. Miscellaneous Property in Sec.	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 07/07/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(A10) Quarter corner common to Section 30 T45N-R31W and Section 25 T45N-R32W. 1971 - Reestablished by A.O.Enger RLS by proportionate measurement on line between original section corner 40.115 ch. South and original 1/4 corner 80.229 ch. North. Found rotted sugar maple stump N19°W 26 links, possibly an original BT, but no marks. Set 1"IDx36" I.pipe with 4" alum. cap. Balsam 8" N14°W 51.5 links, Sugar Maple 8" S29°E 22 links.

(B10) Center of Section 30. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A10) Found the 1971 monument in good condition and at record bearing and distance from the remaining NBT Sugar Maple S29°E, in good condition, with blazes overgrown. The monument was found substantially at the proportionate position between corners A9 and A11 (as per previous records) and I accept same as a careful and faithful reestablishment of the position of the original corner.

(B10) Established the position for the corner at the intersection of straight lines connecting opposite 1/4 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A10) Found 1"ID I.pipe with 4" alum. MI Dept of Conservation cap. Set measuring nail with MDNR tag in the side of:
11" Sugar S30°E 14.95' old blazes (1971 NBT)
6" Sugar N67°W 7.2' mrkd "1/4S NBT"
9" Sugar N06°E 10.6' do
11" Sugar N87°E 10.25' do
Set sq'd cedar post adjacent.
E= 7904249.094 N= 165785.203

(B10) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
9" Sugar N57°E 4.45' mrkd "C1/4 BT"
11" Maple S05°W 15.65' do
6" Sugar S74°W 15.4' do
12" Maple N07°E 12.1' do
Set sq'd cedar post adjacent.
E= 7905045.099 N= 165770.646

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 dat
Coord. Ref.=NGS PID AA8081: N= 147176.690 m. E= 7895147.466 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 08/04/2015

For the Michigan Department of Natural Resources, Forest Resources Division

