

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Iron</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T 45N R 34W	A-10 ✓
	T 45N R 35W	M-10
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:00

L.P. Records: L. 8, P. 238

*Edward J. Pisoni*  
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

Quarter Corner to Section 25, T45N, R35W  
Quarter Corner to Section 30, T45N, R34W

I, Gary L. Pisoni, in a field survey on March 20, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on September 17, 1846 by William A. Burt, U.S. Deputy Surveyor.

Original Corner; Tamarack Post

Original Bearing Trees:

Spruce	5"	S 67°E	15 links (9.90 feet)
Tamarack	5"	S 38°W	14 links (9.24 feet)

On 8/23/72, Arthur O. Enger RLS DNR restored the quarter corner position by proportionate measurement and set a 1" diameter by 36" long iron pipe with a 4" aluminum cap stamped as follows: T45N, R35W, R34W, 1/4, S-25, S-30, RLS 13581 recorded in Liber 1, Page 273-274 of LC records.

1972 Bearing Trees:

Tamarack	3"	N 59° E	67.0 feet
Tamarack	6"	N 08° W	83.3 feet

PEER GROUP APPROVED

*Iron Gary L. Pisoni 11-30-2000*

COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

On 3/20/2000 found monument as described above and the following bearing trees:

Tamarack	7"	N 63°E	67.17 feet
Tamarack	7"	N 05°W	83.30 feet

Found existing bearing tree established by the U.S.F.S.

Black Spruce	5"	N 31°W	45.91 feet
--------------	----	--------	------------

Monument is 4" above ground surface.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree)

Tamarack	8"	S 59°E	55.91 feet
Steel sign post		S 80° W	0.7 feet

00-006

Signed by Gary L. Pisoni Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY, 14, 1976  
REVISED JAN., 1983  
REVISED OCT., 1995