LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

| Fo | rco | rne | rs in |
|----|-----|-----|-------|
| | | | |

| [ron (County) | Located in: | Corner Code # | |
|--|--|---|---|
| 1. Public Land Survey | T 46N R 33W T R | C10 (GCDB 200240) | |
| 2. Property Controlling in Section | S 32 T 46N R 33W S T R | 3 (GCDB 200160) | |
| 3. Miscellaneous Property in Sec. | S T R S T R | | Posister of Deede Chann 9 File Manha |
| 4. Lot No. , Red 5. Private Claims | corded Plat | 0/00/45 | Register of Deeds Stamp & File Number |
| above were in conformance with a instructions of the United States I a Court of Law and /or that the | 74, Michigan P.A. of 1970, the corner regulations and rules therefore as requipe Department of the Interior, Bureau of Ecorner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree | ired in the current manual of survey Land Management or by a decree of the 5 above were in conformance with | y 5 of 6181716151413 oh 7 |
| NOTE: Not more than 2 corn on this certificate. | ners, all in the same town and rang | e, may be recorded | 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36 |

A. Description of original monument and accessories and/or subsequent restoration:

(C10) Quarter corner common to Sections 29 and 30. 1977 - Corner reestablished by A.O.Enger RLS midway and on line between Section corners 2638.34' north and south. Set 1"IDx36" I.pipe with 3 3/4" aluminum cap. Red Maple 10" S46°E 18.7', Y.Birch 13" N84°W 25.0'.

(3-Sec. 32) North 1/16 corner between Section 31 and 32. 1985 - Established by K.L.Sackett RLS midway and on the Section line between Section corner to north and the computed position for the 1/4 corner to south. Set 1"IDx32" I.pipe with 4" alum. MDNR cap. 9" Sugar N08°W 4.1', 8" Sugar S80°W 18.7', 8" Sugar S70°E 26.1'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C10) Found the 1977 monument in good condition and at record bearing and distance from the 1977 accessories. The Maple SE is in good condition with overgrown blazes. The Y.Birch NW is standing dead. The monument was found substantially at the midway position of record: C9 is 2636.21' N, C11 is 2636.21' S, C10 is 0.13' east of the line. I accept same as a careful and faithful reestablishment of the position of the original corner.

(3-Sec. 32) Found the 1985 monument bent over. Excavated to find the lower portion of the pipe straight and plumb and at record bearing and distance from the 1985 witnesses. The Sugar NW is a stump; the Sugar SE is in good condition with overgrown blazes; the Sugar SW is in good condition with scribing visible. Found the monument to be substantially at the midway position of record, accepted same as a careful and faithful establishment of the position of the corner, and remonumented the corner at the position of the straight and plumb lower portion of the pipe.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

| Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 data Magnetic | |
|---|----------|
| Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m. | |
| Signed by Stephen Syngholi Date 08/06/2015 * STEPHAN J. | |
| Surveyor's Michigan License No. 33986 | |
| For the Michigan Department of Natural Resources, Forest Resources Division | <i> </i> |
| NO. FORM, APPROVED BY, MICHIGAN STATE BOARD ON PROVESSION AS A SECOND OF THE PROVINCE OF THE | 0 |

> ad Jan., 1983 Revised Oct., 1995