

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 20 T 46N R 33W	12 (GCDB 240320)
	S 20 T 46N R 33W	11 (GCDB 220320)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 06/08/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(12-Sec. 20) Center-South 1/16 corner, Section 20. Not previously monumented.

(11-Sec. 20) Southwest 1/16 corner, Section 20. Previously monumented by G.L.Pisoni, PS during a partial subdivision of Section 20, date unknown. Set 5/8" rebar at the intersection of straight lines connecting opposite 1/16 corners.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(12-Sec. 20) Established the position for the corner midway and on a straight line between Quarter corner 1319.30' south and the intersection of 1/4 lines of Section 20 1319.30' north.

(11-Sec. 20) Found a 5/8" dia. rebar, set firmly, substantially at the position of the intersection of straight lines connecting opposite 1/16 corners and accepted same as a careful and faithful establishment of the position of the corner. Drove a plastic cap on top of the rebar.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(12) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
2" Sugar N83°E 13.6' mrkd " X X "  
4" Balsam S25°E 5.9' "1/16S BT"  
6" Aspen N85°E 5.2' do  
3" Sugar N17°W 36.9' do  
Set sq'd cedar post adjacent.  
E= 7887650.555 N= 176933.743

(11) Found 5/8" rebar and set plastic cap "MI DNR PS33986" on top of it. Set measuring nail with MDNR tag in the side of:  
14" W.Spruce S75°E 5.2' mrkd "1/16S BT"  
10" W.Spruce S17°E 11.9' do  
6" Balsam S26°W 14.25' do  
10" Maple N07°W 23.25' do  
Set sq'd cedar post adjacent.  
E= 7887249.828 N= 176942.717

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.  
Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Signed by Stephan J. Szyszkoski Date 08/06/2015  
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division