## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

[ron	_ Located In:	Corner Code #	
1. Public Land Survey	T 46N R 33W T R T 46N R 33W	D11 (GCDB 240200)	
2. Property Controlling in Section	S T R S T R	(GCDB 240300)	
3. Miscellaneous Property in Sec.	S T R S T R		Decision of Decision Communication
4. Lot No. , Red 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number  A B C D E F G H I J K L
above were in conformance with i	74, Michigan P.A. of 1970, the corner regulations and rules therefore as require	3 4 7 8 9 10 11 12- 12 5	
a Court of Law and /or that the c	Department of the Interior, Bureau of Lorner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree ered, found as expressed below:	ith 7	
NOTE: Not more than 2 corn on this certificate.	ers, all in the same town and range	e, may be recorded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
			13

A. Description of original monument and accessories and/or subsequent restoration:

(D11) Quarter corner common to Sections 29 and 32. 1933 - Buell and Seppala of Northern Paper Mills found post and original Y.Birch BT I.M. plain; 1951 - Dean C. DeLaMater RLS for the MI Dept. of Conservation remonumented the corner from an original B.T., in good condition. Set 1" pipe with 4" brass cap. 12" Hemlock S45°E 27 links, 14" Hemlock S80°W 32 links.

(D9) Quarter corner common to Sections 20 and 29. 1985 - Reestablished by K.L.Sackett RLS midway and on line between Section corners. Set 1"IDx32" I.pipe with 4" alum. cap. 14" Spruce N76°W 7.3', 9" Spruce S38°W 20.2'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D11) Found the 1951 monument in good condition and at record bearing and distance from the 1951 Hemlock NBTs as well as from the remains of the original Y.Birch BT N38°E 46 links, dead and standing with scribing visible. The 1951 Hemlock SW is standing dead. The 1951 Hemlock SE is in good condition with overgrown blazes. Accepted the monument as a careful and faithful perpetuation of the position of the original corner.

(D9) Found the 1985 monument in good condition and at record bearing and distance from the 1985 witnesses. The Spruce SW is in good condition with overgrown blazes. The Spruce NW was found cut down fairly recently. The monument is substantially at the midway position of record and I accepted same as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D11) Found 1"ID I.pipe with 4" brass MI Dept. of		
Conservation cap. Set measuring nail with MDNR tag in the side of:  17" Hemlock S46°E 18.35' old blazes (1951 NBT)  16" Hemlock S58°W 21.3' mrkd "1/4S NBT"  7" Sugar N39°W 13.45' do  7" Sugar N06°E 18.5' do  Found a 3/4" mushroomed I.pipe, bent, N28W 6.05'  Set sq'd cedar post adjacent.  E= 7887605.151 N= 174924.956	(D9) Found 1"ID I.pipe we set measuring nail with M 10" Spruce S45°W 20.4' 7" Spruce N77°E 20.9' 11" Spruce N80°W 29.2' 3" Spruce N01°W 22.4' Set sq'd cedar post adjace = 7887643.178 N= 17653	MDNR tag in the side of: old blazes (1985 NBT) mrkd "1/4S NBT" do do cent.

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 date Coord. Ref.=NGS PID RL0476: N= 196482 411 m OF MICH

oogra.	MOLI-MOD LID	KEGA10.	TA =	130404.411 III.	ഥ=	7879234.516	m.
	2 0	1					
	(1 //						
 1 - 1	V - V .						

Signed by & lepha Surveyor's Michigan Licénse No. 33986

Date

08/06/2015

For the Michigan Department of Natural Resources, Forest Resources Division

SÜRVEYOR No. WBBBB FORM APPROVED BY MICHIGAN STATE BOARD OF AND

STEPHAN J

<del>Szyszkoski</del>

LAND