

For corners in

Corner Code #

(County)

1. Public Land Survey

T. 27N R. 6W

E-5

2. Property Controlling in Section

S T B

S T R

S_____T_____R_____

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims

I, EUGENE FARRIER, in a field survey on December 12, 20 00 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-5: Sec. Cor. Common to Secs. 8, 9, 16 & 17, T27N-R6W, Excelsior Township

1852, G.L.O. Resurvey, by George H. Cannon, set post for corner; Sugar 6", N47°W, 30 Lks; Sugar 8", S30°E, 6 Lks

1895, Survey, by E.B. Dinnis (Co. Surveyor), no stake was found

1898, Survey, by E. Mosher (Co. Surveyor) Bk 5, Pg 34, Sugar 16", N65°W, 11 Lks; Hemlock 10", S26°E, 18 Lks

1971, Survey, by N.F. Parker, found ½" iron bar in centerline road intersection, County Road sign post, N26°E, 52.50'; telephone pole. S22°E, 84.0'

1974, LCRC, by L. Gerschbacher, Liber 1, Pg 300A, found cabin spike, no accessories available

1974, LCRC, by H.L. Fluaharty, Liber 1, Pg 325, found 5/8" iron; guard rail post (North end of East side of road)) S10°E, 76.32'; East end 15" tube, N26°E, 71.45'; West end 15" tube, N25°W, 76.16'

1974, Survey, by H.L. Fluharty, Liber 1, Pg 571, same as LCRC, Liber 1, Pg 325

1976, Survey, by J.L. Fletcher, Liber 1, Pg 936, set 1/2" iron & cap; nail in guard post N27°W, 76.06'; guard rail post S09°E, 76.27'; + in CMP, N32°E. 71.29'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-5: Sec. Cor. Common to Secs. 8, 9, 16 & 17, T27N-R6W, Excelsior Township

Found 3/4" iron bar in mon box in centerline 571 & Highway 612 to West Grass Lake Road to East. Added brass remon cap
No G.L.O. witnesses were found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-5: Sec. Cor. Common to Secs. 8, 9, 16 & 17, T27N-R6W, Excelsior Township

Found 3/4" iron bar in man box in centerline 571 & Highway 612 to West Grass Lake Road to East. Added brass remon cap

N17°E, 224.66', power pole, set nail & tag East side

S50°E, 75.41', power pole, set nail & tag NE side

S87°W, 253.14', power pole, set nail & tag North side

N55°W, 70.99', set nail & tag SW side

South, 1.00', PK set

East, 1.00', PK set

Kalkaska County Peer Group accepted the above monument as the best available evidence of the position of the original corner.

Ratified by Peer Group

P.A. 345 - 1990 Kankaska County

Chairman James L. White

Date 2-14-01

Signed by [Signature]
Surveyor's Michigan License No. 24594

Date 2-15-01



3026832

Page: 1 of 1
02/16/2001 10:26A
REMON
LB: 6 PG: 161

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1986

