## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

REGISTER'S OFFICE For corners in County of Keweenaw Keweenaw County Corner Code # Located in: Received for Record, the day of October A.D. 2000 1. Public Land Survey T56N R30W M.C. 4 V T56N R30W M.C. 5 at 11:00 o'clock A. M., and Recorded Т R in Liber T R 2. Property Controlling Т R on page S in Section S Т R Miscellaneous S T R SURVEY & Register of Deeds s Property in Sec. REMONUMENTATION Register of Deeds Stamp & File Number £ G H , Recorded Plat R c Đ F 1 4 1 of No A FEB 07 2001 5. Private Claims 2 3 SECTION 4 5 I, Steven C. Hein, in a field survey on May 26, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in 6 conformance with regulations and rules therefore as required in the current manual of survey 7 instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court 8 20 22 23 24 of Law; established, re-established, monumented, recovered, found as expressed below: 9 10 Not more than 2 corners, all in the same town and range, may be recorded 11 on this certificate. 12 32

- A. Description of original monument and accessories and/or subsequent restoration:
  - M.C. 4: Meander Corner between Sections 9 & 10: From original notes: South true line between Sections 9 & 10; 72.82 to Lake Mark Meander Corner on Spruce at high water mark: Spruce 6 N90W 21: do 6 N80E 14. No evidence of original corner or accessories found.
  - M.C. 5: Meander Corner between Sections 9 & 16: From original notes: East true line between Sections 9 & 16; 71.71 Set post Meander Corner on margin of Lake at high water mark; Tamarack 8 S60W 17; do 6 N10W 23. No evidence of original corner or accessories.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - M.C. 4: Meander Corner between Sections 9 & 10: No evidence found. Established corner near high water mark on line through the E1/4 Corner Section 9 from the NE. Corner Section 9 (S00°44'27"E).
  - M.C. 5: Meander Corner Sections 9 & 16: Found 1/2" capped pin, P.S. 39478 set by R. S. Haataja in his survey dated September 27, 1999. No witnesses found.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M.C. 4: Meander Corner Sections 9 & 10: Set 4" Brass Cap stamped for corner on 1" pipe, 75' South to Lake Witnesses: 14" W. Pine N22°E 36.86' 8" W. Birch S85°E 15.04'

9" W. Birch S30°W 23.10'

6" Spruce N83°W 14.07'

M.C. 5: Meander Corner Sections 9 & 16 Replaced 1/2" capped pin with 4" Brass Cap stamped for corner on 1" pipe, 200 ' East to Lake Witnesses:

1.3

9" Cedar N22°E 44.19' 1/2" pin N88°23'37"E 64.06' 5/8" pipe N32°W 31.57 8" R. Maple N17°W 47.45'

Bearings are compass bearings, corrected for declination, all distances are to a nail and tag in the side of the witness object unless otherwise noted.

STEVEN 於 C. HEIN **PROFESSIONAL** SURVEYOR No.

Ratified by Peer Group In accordance with P.

Co. Rep. 🕊

Signed by 32336 Surveyor's Michigan License No.

OCTOBER