

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Keweenaw (County)	Located In:	Corner Code #
1. Public Land Survey	T 56N R 31W	MC 5
	T R	
	T R	
2. Property Controlling in Section	S 34 T 56N R 31W	SMC South of H12
	T R	
	T R	
3. Miscellaneous Property in Sec.	S T R	
	T R	
	T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 09/16/13 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(SMC south of H12) Special Meander Corner set at the Lake Superior shore on the N-S 1/4 line of Section 34. Not previously monumented.

(MC 5) Meander Corner on the South line of Sec. 34. Corner remonumented 10/9/2007 by Steven C. Hein PS 32336, approved by Keweenaw County Peer Group 12/04/2007 and fully described and recorded in Liber 2 of LCR, Page 253, Keweenaw County Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(SMC) Established the position for the corner on the N-S 1/4 line of Sec. 34, having a bearing which is the weighted mean bearing of the east and west Section lines, and 1840.00' south of the monumented Center of Section 34. The corner falls 22' south of a swamp edge and lies on the northern edge of a 2.5' high berm which supports emerging vegetation. The northing is a position of convenience. I did not attempt to mark the Ordinary High Water Mark of Lake Superior.

(MC 5) Found the 2007 monument of record, in good condition and at record bearing and distance from the 9" forked Tamarack NBT and the 1" pipe on the section line. The 3" W.Birch and 2" Spruce NBTs were not recovered. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(SMC) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
3" Tamarack N24°E 21.75' mrkd "SMC BT"
10" Tamarack N67°E 55.2' do
8" Tamarack S09°W 34.95' do
3" Tamarack S84°W 76.7' do
Set sq'd cedar post adjacent.
E= 7907212.996 N= 269578.585

(MC 5) Found 3.25" dia. Keweenaw Co. remonumentation cap on 5/8" dia. Iron pin. Found nail and tag in:
9" forked Tamarack N44°E 314.90'
Fd. 1" iron pipe, flush, N88°W 45.0'
Set measuring nail with MDNR tag in the side of:
3" W.Birch N03°W 20.15'
2" W.Birch N37°E 29.1'
1.25"x6' long pipe, 4' a.g. adjacent, N40°E 0.5'
E= 7906958.742 N= 269353.030

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).

Coord. Ref.=USACE monument "RAMP 1995": N= 268244.768 m. E= 7906171.601 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 10/02/2013

For the Michigan Department of Natural Resources, Forest Resources Division

