LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Lake (County)		Loc	cated In	Corner Code #	
1. Public Land Survey		т Т	R		
Property Controlling in Section	S 28	_ `	3N R 12W	8	
Miscellaneous Property in Section	\$ <u>28</u> \$	_ ^Т _1	R 12W R R R R R	15	Register of Deeds Stamp & File Number
4. Lot No: 5. Private Claims:	Record	ed Plat:			A B C D E F G H I J K L M
I, Craig W. McVean, in a f requirements of PA 74, Mi and 2 above were in confo the current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of established.	chigan PA mance wit vey instruct nagement lines 3, 4 a f Land Su , monumen	of 1970, th regulations of or by a do and 5 about the contract of the contract	the corner points ons and rules the United State ecree of a Court over were in confor by a Decree vered, found as e	mentioned in lines 1 erefore as required in its Department of the of Law and/or that the rmance with the rules of a Court of Law; expressed below:	3 4 - 7 - 8 - 9 - 10 - 11 - 12 - 15 - 14 - 13 - 17 - 16 - 15 - 14 - 13 - 17 - 18 - 19 - 20 - 21 - 22 - 23 - 24 - 9
NOTE: Not more than 2 corners, all in the same town and range, may					

- A. Description of original monument and accessories and/or subsequent restoration:
- 8-1978-LCRC-L. 2, p. 336-C. F. Roser Set 5/8" x 40" rod with RLS cap in centerline E-W Road.
 - 1) 4" B. Oak N43°E 29.92'

be recorded on this certificate.

- 2) 5" B. Oak S15°E 49.07
- 3) Fd. 3/4" pipe South 33'

- 15 1925 Plat of "Blass Park" in file case of plats, Drawer 8, by G. Johnson – 1" x 20" pipe - 1958 – Plat of "Cherry Valley Community" L. 2 of plats,
 - page 33. George Blass shows corner
 - 1978 LCRC L. 2, p. 336 C. F. Roser Fd. 3/4" iron 2' South of centerline of E-W road.
 - 1) 12" B. Oak N15°W 42.26'
 - 2) 9" B. Oak S02°W 32.87'
 - 3) Set Cedar Post with location tag N 33'
- B. Description of comer evidence found and/or method applied in restoring or re-establishing corner:
- 8 CW 1/16 Comer Section 28 Found 5/8" capped iron rod #12028 in centerline E-W gravel road. All three witnesses in good shape. 5/8" CIR accepted as the best available evidence of the position of the corner.
- 15 W 1/16 Corner common to Sections 28 and 33 Fd. broken plastic cap # 12028 on 5/8" rebar - 2' South of centerline of E-W gravel road. Witness #1 was blown down and #2 in good shape. Cedar post fallen over. 5/8" CIR accepted as the best available evidence of the position of the corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 8 5/8" rebar with broken plastic cap N44°E 29.75' to set nail and tag @ reaction in SE side 13" Oak (#1) S15°E 49.08' to set nail and tag @ found nail in E. side 10" Oak (#2) N20°W 31.33' to set nail and tag in E. side 5" Oak South 33.04' to fd. 1 1/4" O.D. iron pipe South 32.92' to fd. 3/4" O.D. iron pipe

North 32.6' to Cedar post with loc. tag

Surveyor's Michigan License No.:

39088

15 - 5/8" capped rebar #12024. North 33.00' to set 2" Aluminum cap on 5/8" x 34" rebar on line with Blue Carsonite Post with loc. tag. N48°W 41.86' to set nail and tag in SW side Power Pole S02°W 32.84' to set nail and tag in W. side 13" W. Oak (#2) N49°E 44.93' to set nail and tag in NW side 5" J. Pine

> OF MICHIGAN CRAIG W. **McVEAN PROFESSIONAL** 12011 SURVEYOR No. MOPESSION.