1993

## COMMISSION

## REMONUMENTATION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 RECEIVED FOR RECORD

For corners in	3 444	Total Table 1 4, Illian 1 .	MEGELMER LAW MENTAL
LAPEER (County)	Located In:	Corner Code ##	93 DEC 30 AM 10: 21
1. Public Land Survey	T <u>6 N R 9 E</u> T R T R	M-11	LIBER NO 5 LA NO 3  Melissa Miles REPOSITE TO THE TOTAL
2. Property Controlling in Section	S T R S T R		A STATE OF THE STA
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
	ecorded Plat		A B CA D E, F G H A J K L N
do hereby certify that under requinitines 1 and 2 above were in current manual of survey instru Management or by a decree of a above were in conformance with Court of Law; established, reexpressed below:	in a field survey on Novembuirements of P.A. 74, Michigan P.A. conformance with regulations a ctions of the United States Department of Law and/or that the corn the rules of the Michigan Board e-established, monumented, re-	A. of 1970, the corner points mention rules therefore as required in the interior, Bureau of the Interior, Bureau of the points mentioned in lines 3, 4 a of Land Surveyors or by a Decree-monumented, recovered, found	oned on the fand of the fand o
NOTE: Not more than 4 co on this certificate.	orners, all in the same town a	and range, may be recorded	11 12 31 32 33 34 35 36
A. Description of original n	nonument and accessories ar	nd/or subsequent restoration:	

- 1817 GLO Wampler, D.S.; Set post; 8" Elm S65°W 13 lks; 12" Red Oak NO9'W 40 lks
- 1972 Henderson, P.S. #16043; Survey L.1, Pg.752 Fnd 1/2" iron rod; Same wits as LCRC
- 1978 Elrich, P.S. #16699; Survey L.4, Pg.517 Fnd railroad spike
- 1980 Elrich, P.S. #18986; Survey L.5, Pg.624 Fnd railroad spike
- 1984 Ankrom, P.S. #21265; LCRC L.4, Pg.63 Set 1/2" iron rod replacing railroad spike
- 1986 Elrich, P.S. #16699; Survey L.7, Pg.239 Fd. iron rod
- 1991 Bates, P.S. #16699; Survey L.9, Pg.486-469 Fnd railroad spike; Same wits as 1980 survey
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - 1993 Kennedy Surveying, Inc. Kennedy, P.S. #17623 Fnd 1/2" iron rod 2'± East of the center of Baldwin Road and 6'± North of the center of Brauer Road. Both are gravel roads.

The witnesses in the power poles are still existing. They were used to recover the found 1/2" iron rod. A second 1/2" iron rod was found 6' + South and 1.5' + West of the Section Corner. This is the Southwest Corner Section 30 for Metamora Township.

- I accepted the find 1/2" iron rod to the North as the best evidence of being the original corner position.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-11 1/2" x 24" iron rod with 3" diameter brass cap

N21°W 105.00' Set nail w/remon. tag West face 32" Oak

N51°W 75.51' Set nail w/remon. tag above existing witness South face Power Pole

\$78°W 120.40' Set nail w/remon. tag North face 16" Ash

N39°E 56.70' Set nail w/remon. tag above existing witness SE face Power Pole

S11°E 145.92' Set nail w/remon. tag West face 8", 9", 12" Triple Elm

E OF MICH KENNEDY LAND

Surveyor's Michigan License No.

11/24/93

FORM APPROYED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

LISER 005 PAGE 53

REVISED MAY 14, 1975 REVISED JAN., 1983