JAM2 : 2000

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 INER 1 PAGE 317

STATE	Œ	HICHIG	1
LEN	AVE	COUNT'	ĺ
	511	ED	

For corners in	Located In:	Corner Code #	LERANCE CURRET FILED
Lenawee (County)	Located III.	Come: Code #	14 JUL 1999 6:31:35 PN
1. Public Land Survey	T <u>-5-S</u> R <u>-5-E</u> T R T R T R	<u>G-6</u>	VICTORIA J. DANIELS REGISTER OF DEEDS
 Property Controlling in Section Miscellaneous Property in Sec 	S T R S T R S T R S T R		Register of Deeds Stamp & File Number
4. Lot No, F 5. Private Claims	Recorded Plat		A B C D E F G H I J K L M
do hereby certify that under in lines 1 and 2 above wer current manual of survey ins Management or by a decree above were in conformance	, in a field s requirements of P.A. 74, Michigan P. e in conformance with regulations e structions of the United States Depa of a Court of Law and/or that the cor- with the rules of the Michigan Board d, re-established, monumented, re-	A. of 1970, the corner points men and rules therefore as required atment of the Interior, Bureau of the points mentioned in lines 3, 4 at of Land Surveyors or by a Decre	199, 5 stioned 6 18 17 6 15 14 13 in the Land 7 and 5 8 ee of a and as 10 30 20 28 27 26 25
NOTE: Not more than on this certific	4 corners, all in the same towate.	vn and range, may be reco	rded 12 31 32 33 34 35 36

Description of original monument and accessories and/or subsequent restoration:

G.L.O. 1819 Joseph Fletcher set 1/4 Sec. post Lynn 4 N 16 W 7 W. Oak 12 N 81 W 21 1940 Harold Clegg surveyed for bridge on Britton Hwy, and his notes call for boat spike 1973 Werner Sommer found boat spike raised with 3/4" iron pipe & recorded it in L2 P 321 1990 Survey by W.E. Frazier and Assoc. did survey in SE corner NE 1/4 of Section 16 and show corner as recorded.

1997 I found 60 d spike over iron pipe which was over boat spike 2' deep. Replaced it with 3/4" X 3' iron pipe and set monument box in newly layed asphalt pavement.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

July 6, 1999 Found 3/4" iron pipe in monument box. Drove the iron pipe down with 5/8" X 3' re-rod inside of it and capped with Lenawee County Re-mon cap stamped P.S. 13040

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

I.P. capped W.E.F. 17636 West 32.90 Fd nail & washer on N. side E.P. N 55° E 28.26 dbl hd nail & Lenawee County Re-mon tag in E. face 13" Elm N 60° W 36.24 Cut "X" on CMP N 15° E 75.90



	NOVERNAMEN
Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Henne Pulmal	Date <u>June 22, 1999</u>
Signed by Slenn & Richard Date July 8, 1999 Glenn E. Richard	
Surveyor's Michigan License No. <u>13040</u>	FORM APPROVED BY MICHIGAN STATE BOARD OF

LAND SURVEYORS, JAN. 28, 1971