LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Luce	Located In:	Corner Code #			
(County)	***	Somer Gode #			
1. Public Land Survey	T R R				
2. Property Controlling in Section	S 36 T 45N R 10W S 36 T 45N R 10W	L12 8	28		
3. Miscellaneous Property in Sec.	S T R S T R			19	
4. Lot No. Reco	orded Plat		Register of Deeds	Stamp & File Num	ber K L
	L12 12/2	21/2011	2 5 5	32	
i, Stephan J. Szyszkoski, in a that under requirements of P.A. 7- above were in conformance with re		18/2012 do hereby state	3 4 7 8 5	91011	
instructions of the United States De	epartment of the Interior, Bureau of La	and Management or by a decree of	6 10 17	16 15 1	13

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

re-established, monumented, recovered, found as expressed below:

A. Description of original monument and accessories and/or subsequent restoration:

a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, a

(L12) Center of Section 36. Established in 1969 by Billy D. Buckler RLS at the intersection of 1/4 lines. Set 1" pipe with 4" aluminum cap. 14" Beech S25E 21.5', 14" Beech N31E 15.3'.

(8-Sec. 36) West 1/16 corner, Section 36. 1969 - Established by Billy D. Buckler RLS midway between Center of Section to East and Quarter corner to west. Set 1" pipe with 4" aluminum cap. 12" W.Pine N50E 22.3', 18" W.Pine S13W 54.3'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(L12) Found the 1969 monument in good condition, at substantially the record position, and at record bearing and distance from one remaining witness, the Beech N31E 15.3', in good condition. Accepted the monument as a careful and faithful establishment of the position of the corner.

(8-Sec. 36) Found the 1969 monument, leaning and with broken cap. The 1969 witnesses are in place and in good condition. Plumbed the monument and made firm so as to be in accord with the record bearing and distance to the 1969 witnesses. The monument was found at substantially the record position and is accepted as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(L12) Fd. 1"ID I.pipe with 4" alum. MI Dept. of (8) Fd. 1"ID I.pipe with broken aluminum cap. Conservation cap. Set measuring nail with MDNR tag in the side of: Set measuring nail with MDNR tag in the side of: 24" W.Pine N53E 23.3' mrkd "W1/16" 1969 BT 16" Beech N42E 15.8' mrkd "CS" 1969 BT 23" W.Pine S24W 54.55 do 11" Maple N28W 16.2' "CS BT" 12" Sugar S89E 10.7' mrkd "W1/16 BT" 8" Sugar S77E 13.35' do 14" Sugar N23W 18.05' 14" Sugar S53W 42.7' do A chrome running board is adjacent. Bearings are magnetic. Bearings are magnetic.

Signed by

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources, Forest Resources Division

Date

10

11

12

07/12/2012

FORM APPROVED BY MICHIGAN STATE BOARD

STEPHAN J SZYSZKOSKI LAND SURVEYOR

33986

FESSIONAL SUR

Rervised Oct., 1995

47529 47530

vised May 14, 1975 Revised Jan., 1983