LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

on this certificate.

Luce	_ Located In:	Corner Code #	
(County)			
1. Public Land Survey	TR TR		
2. Property Controlling in Section	S 33 T 45N R 10W S 33 T 45N R 10W S T R	1 4	
3. Miscellaneous Property in Sec.	S T R		
4. Lot No. 5. Private Claims , Rec	corded Plat1 05	/02/2011	Register of Deeds Stamp & File Number A B C D E F G H I J K L 2 - 6 - 5 - 4 - 3 - 2 - 1
I, Stephan J. Szyszkoski , in that under requirements of P.A.	74, Michigan P.A. of 1970, the corner	/02/2011 do hereby state	3 9 10 11 12
above were in conformance with r	regulations and rules therefore as requi	fred in the current manual of survey	,⁵├ ─┼─┼─┼─┼─┼─┼─
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8			
re-established, monumented, recove	ered, found as expressed below:	e or a Court of Law; established,	9 - 20 - 21 - 22 - 23 - 24 -
NOTE: Not more than 2 corn	ers, all in the same town and range	e, may be recorded	10 30 29 28 27 26 25

A. Description of original monument and accessories and/or subsequent restoration:

(1-Sec. 33) West 1/16 corner between Sections 28 and 33. 1977 - Established by Billy D. Buckler RLS midway between 1/4 corner to east and Section corner to west. Set 1"ID I.pipe with 4" alum. cap. 20" Maple S10W 27.7', 18" Beech N37E 26.4'.

(4-Sec. 33) Northwest 1/16 corner, Section 33. 1977 - Established by Billy D. Buckler RLS at the intersection of 1/16 lines. Set 1" pipe with 4" aluminum cap. 16" Soft Maple S85W 29.2', 8" B.Cherry S84E 3.2'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(1-Sec. 33) Found the 1977 monument in good condition and at record bearing and distance from the 1977 witnesses. The Maple is in good condition, the Beech is now dead. Accepted the monument as a careful and faithful determination of the position of the corner.

(4-Sec. 33) Found the 1977 monument in good condition and at record bearing and distance from the 1977 witnesses, both in good condition. Accepted the monument as a careful and faithful determination of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(1) Fd. 1"ID I.pipe with 4" aluminum cap. Set measuring nail with MDNR tag in the side of: 25" Maple S12W 28.8' mrkd "W1/16" 1977 BT 8" Cherry N15W 10.75' "W1/16 BT" 8" Sugar S47W 8.55' do 5" Sugar S63E 10.45' do Bearings are magnetic.

(4) Fd. 1"ID I.pipe with 4" aluminum cap. Set measuring nail with MDNR tag in the side of: 16" Cherry S80E 3.75' mrkd "NW1/16" 1977 BT 19" Maple N89W 29.85' do do 5" Sugar S43W 5.8' mrkd "NW1/16 BT" 8" Cherry N61E 12.25' do Bearings are magnetic.

Signed by Surveyor's Michigan License No. 33986 For the Michigan Department of Natural Resources, Forest Management Division

06/15/2011

Date

ZYSZKQSKI LAND

STEPHAN J

SURVEYOR

TAND W

OF MICH

No. 39

47484

47485

FORM APPROVED BY MICHIGAN STATE BOARD

sed Jan., 1983 Rervised Oct., 1995