

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF—	LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. <u>46</u> N. <u>2</u> R. <u>9</u> W.	<u>1-1</u>
2. PROPERTY CONTROLLING IN SECTION	T. _____ N. _____ R. _____ E. _____	_____
3. MISCELLANEOUS PROPERTY IN SECTION	T. _____ N. _____ R. _____ E. _____	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 11/6 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
Original township corner of towns', 46-47 North, ranges' 8-9 West, set June 30, 1844 by Wm. A. Hart, D.S.

Bearings and Distances:
12" Cedar S40°E 33 Links and Cedar 10" S17°W 13 Links

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
Found a certified steel post by W. Lawrence, L.L.S. found remains of Cedar S.T. in proper position, down and badly rotted. No evidence of Birch S.T.

Found remains of a naillock, apparently marked by Lawrence about 40 years ago. Tree is down, rotted with a face and scribe marks "T47N R8W S31", stump bears N46°E, 5.0'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Placed 1" pipe with 4" aluminium cap at corner.

New Bearings:
10" Soft Maple S55°E 36.8'
12" Cedar S57°E 28.6'

SIGNED BY Billy D. Buckler
Billy D. Buckler

DATE 11/6/72

SURVEYOR'S MICHIGAN REGISTRATION NO. 8847

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ CHIEF OF SURVEY PARTY

DATE _____

APPROVED AND SIGNED BY _____

MICHIGAN REGISTERED LAND SURVEYOR

DATE _____

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.

Form No. M735
FOURTEEN APRIL 1971

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN 28 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS