## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Luce (County)	Located In:	Corner Code #	
1. Public Land Survey	T 47N R 09W T R 09W	B13 (GCDB 140100)	
2. Property Controlling in Section	S T R S T R	C12 (GCDB 200140)	
3. Miscellaneous Property in Sec.	S T R S T R		
4. Lot No , Recorded Plat			Register of Deeds Stamp & File Number
5. Private Claims			1 A B C D E F G H I J K L I
above were in conformance with re- instructions of the United States Do a Court of Law and /or that the co	4, Michigan P.A. of 1970, the corner po- egulations and rules therefore as required epartment of the Interior, Bureau of Lan orner points mentioned in lines 3, 4 and 5 of Land Surveyors or by a Decree of	do hereby state  oints mentioned in lines 1 and 2  I in the current manual of survey  d Management or by a decree of  above were in conformance with  of a Court of Law; established,	5 6 18 17 16 15 14 13
NOTE: Not more than 2 corne on this certificate.	ers, all in the same town and range, I	may be recorded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:			

- (B13) Quarter corner common to Section 31 T47N-R09W and Section 6 T46N-R09W. 1963 Reestablished by Billy D. Buckler RLS by proportionate measurement along the township line. Set 1" pipe with 4" aluminum cap. 8" Cedar N46°W 36 links, 8" Cedar S01°E 29 links.
- (C12) Quarter corner common to Sections 31 and 32. 1963 Reestablished by Billy D. Buckler RLS midway and on a straight line between Section corners. Set 1"ID I.pipe with 4" aluminum cap. 8" J.Pine N71°W 19 links, 6" J.Pine N13°E 14 links.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (B13) Found the 1963 monument in good condition and at record bearing and distance from both 1963 NBTs. The Cedar NW is in good condition with open blazes. The Cedar SE is dead. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.
- (C12) Found the 1963 monument in good condition, at record bearing and distance from the 1963 NBTs, now both standing dead. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(B13) Found 1"ID I.pipe with 4" alum. MI Dept of Conservation cap. Set measuring nail with MDNR tag Conservation cap. Set measuring nail with MDNR in the side of: 10" Cedar N43°W 23.97' old blazes (1963 NBT) 8" B.Spruce S32°W 7.85' mrkd "1/4S NBT" 6" Cedar S24°E 17.82' do 4" Maple in clump N22°E 14.63' no scribing E= 8116894.930 N= 182919.725

(C12) Found 1"ID I.pipe with 4" alum. MI Dept. of tag in the side of:

5" B.Spruce S86°W 14.70' mrkd "1/4S NBT" 8" J.Pine N15°W 11.06' do 5" J.Pine N80°E 19.82' đo 6" J.Pine S18°E 22.15' do E= 8117684.268 N= 183742.087

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum OF MICH

Coord. Ref.=NGS PID RJ0491: N= 184295.144 m. E= 8114483.019 m.

Surveyor's Michigan License No.

Signed by

33986

Date

11/04/2015

For the Michigan Department of Natural Resources, Forest Resources Division

STEPHAN J. SZYSZKOSKI LAND SURVEYOR No. Baara AND SU

Revised Oct., 1995

FORM APPROVED BY MICHIGAN STATE BOARD OF