## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Mackinac										
(County)	Located In:	Corner Code #								
1. Public Land Survey	'—	2H C7								
2. Property Controlling	TR_ TR_ S TR_									
in Section	STR									
Miscellaneous     Property in Sec.	S IR									
r reporty in ooo.	· ·			R	egiste	er of De	eds Sta	amp &	File N	lumber
4. Lot No, Recor			<u> </u>	, A	в с	D E	FG	н :	IJ	K L I
		un 30 2004		2		[	ŢŢ		Ţ	
		ul 01 2004		3	_ <u> </u>	1		_[_]		
, Stephan J. Szyszkoski	, in a field survey on	, 19 do here	by state that under	4 -	- 7	8 <del></del>		10	11-	12
requirements of P.A. 74, Michiga	in P.A. of 1970, the corner i	points mentioned in lines 1 a	nd 2 above were in				_   _			
conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or						_  _17	16	1.5	[ 14-	 13
that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented										
recovered, found as expressed be	elow:	,, , , , , , , , , , , , , , ,	,	8 —	19	2O	21	22	23_	_ <del> </del> _24_
NOTE: Not more than 2 corr	ners, all in the same town a	and range, may be recorde	d	9	$\perp$	$\dashv$				
on this certificate.			_	10—	-30	_29	<u>28</u>	<u>2</u> 7	—2 <del>6</del> -	25
				11						+
				12	31-	<b>—3</b> <sup>1</sup> 2	_3 3	_34_	<u> </u>	36
A Description of original mo (C7) Corner common to Section corners 1 mile North and Sout recovered, rewitnessed and re placed plastic cap atop. 6" (87) Quarter corner common to Set post for 1/4 section corn	h. The position fell in recorded in absence of Balsam M56E 52.2', 8°C Sections 18-19. 1849:	the center of N-S grad measurements to adjacen edar S54E 28.65', 8" Ce Established by Guy Car	e. Set 5/8"x16" t corners by the dar S11E 69.9', leton: "East cor	iron ba unders: 5" Maple rected l	ar. 2 igned. e S87V betwee	2002: . Foun 1 35.55 en Sect	The 1969 d 5/8" :	9 monum iron ba	ent w ir and	as !
B. Description of corner evid     (C7) The 1969 monument of rec		=	_		Mr D	luch lar	had mad	da .a	nithm	
error in his 1969 calculation than it actually was on the g by double proportionate measu South (80.00 R), and 80.6539 (true brg), 55.83' distant. (87) The original post and acoriginal record and on the second	s which led him to beli- round. Consequently, h rement to the original ch. East (80.80 R). Lef cessories were not reco	eve that the corner 1 m is proportionate position record between Section of t the 1969 monument in p vered. Reestablished t	ile north of thi on for this corn corners 80.9465 place as a refer ne corner by sin	s positi er is er ch. West ence cor gle prog	ion, a rroned t (81. rner,	it C5, i ous. I 10 R), it beir	reestal 81.4422 ng 583 d	feet f blished 2 ch. N deg. 18	urthe the orth '52"	r west corner and
C. Description of monument	for corner and accessorie	es established to perpetua	ate locating the po	ositio <u>n</u>	the c	offel!	CH / SAC	ie.		
8" Cedar S60W 37.75' "S 12" Cedar N28E 16.0' "S 5/8" iron rod in N-S rd. S88W Bearings are magnetic Distant trees are to nail/tag. * den	nd set MDNR of measu 18 NBT" * 6" Ba 20 NBT" * 6" Ba 17 NBT" 5" Ba 55.83' 6" Ce ces to Beari	lsam \$48E 19.65' lsam N41E 40.6' dar \$67N 59.2'	1/4S MBT" do do do ances are to		STE	PHAN SZKOS LAND RVEY( No. 33986	SKI DR	**		
Signed by Surveyor's Michigan License	sh & Syy	33986	Date	7	<u>/7/</u>	04	<b>-</b>	<u>.                                    </u>	<del></del>	