

MAR 13 1998

SECTION

1997 Mackinac County Remonumentation Corner  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Mackinac  
(County)

Located In:

Corner Code #

- |   |   |            |   |           |            |
|---|---|------------|---|-----------|------------|
| 1. Public Land Survey                   | T | <u>43N</u> | R | <u>1W</u> | <u>G-6</u> |
|   | T |            | R |           |            |
|   | T |            | R |           |            |
|   | T |            | R |           |            |
| 2. Property Controlling<br>in Section   | S |            | T | R         |            |
|   | S |            | T | R         |            |
| 3. Miscellaneous<br>Property in Section | S |            | T | R         |            |
|   | S |            | T | R         |            |
4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

RECEIVED & FILED  
DIANE FRANKOVICH  
MACKINAC COUNTY REGISTER OF DEEDS

DEC 18 1997

AM PM  
7/8/97 11-13/4/5/6

Register of Deeds Stamp & File Number

I, David B. Guthrie, in a field survey on September 23, 1997, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1845: G.L.O. Survey by J.H. Mullet -  
Set Post and Referenced -  
Cedar 12 / N66W / 18  
Cedar 4 / S55E / 14

1994: Survey by Ronald Bischer - Found 1/2" Iron Rod and two witnesses.

Referenced -

N37°E - 12" Cedar - 62.03'

N60°W - 18" Cedar - 59.05'

S67°E - 16" Cedar - 48.11'

S60°W - Utility Pole - 37.55'

L.C.R.C. Recorded in Book D, Page 260

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1997: Remonumentation Survey by R.S. Scott Associates, Inc. - Found 1/2" Iron Rod.

Referenced -

S60°W - Utility Pole - 37.52'

N40°E - 10" Cedar - 62.13'

(Exist.) N66°W - 14" Cedar - 59.15'

S65°E - 14" Cedar - 48.18'

This corner position is compatible with County and local surveys. This corner position is accepted as a careful and faithful perpetuation of the position of the original corner.

ACCEPTED BY SURVEY PEER GROUP  
OFFICIAL CORNER UNDER P.A.  
345 OF 1930 AT A MEETING  
HELD ON 11-21-97

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1997: Placed 3" Mackinac County Cap stamped to identify the corner over 1/2" Iron Rod.

Referenced -

S60°W - Utility Pole - 37.52'

N66°W - 14" Cedar - 59.15'

N40°E - 10" Cedar - 62.13'

S65°E - 14" Cedar - 48.18'



Signed by

*David B. Guthrie*

Date

12-12-97

Surveyor's Michigan License No.

22435

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983