

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970  
Mackinac Co. 3 Corners.

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY.....	T. 43 N. R. 6 X. W.	G-3, G-2, H-3
2. PROPERTY CONTROLLING IN SECTION.....	T. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION.....	T. S. R. E. W.	
4. LOT NO. ...., RECORDED PLAT.....		
5. PRIVATE CLAIMS.....		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 9/14, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:  
All corners set by H. Brevoort Jr., D.S. in 1845.

G-3 Sec. Cor. 3-4-9-10.	G-2 $\frac{1}{4}$ Cor. Bet. Sec's. 3-4.	H-3 $\frac{1}{4}$ Cor. Bet. Sec's. 3-10.
Bearings were:	Bearings were:	Bearings were:
Cedar 16, N32°E, 15 lks.	Balsam 12, S13°W, 14 lks.	Birch 6", S77°W, 22 lks.
Cedar 14, N34°W, 23 lks.	Balsam 12, S17°E, 15 lks.	Tam. 6", N39°E, 13 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G-3 Re-established corner by double prop. measure from corners; 1 mile North; 2 miles South; 1 mile West and 2 miles East. Corner lies in Cedar swamp with numerous old Cedars but none could be identified. Swamp edges fit very good to East and North.

G-2 Re-established corner by Single Prop. Measure bet. two Sec. Cors. Found no evidence of original corner. Corner lies in swamp with numerous pine, cedar, and Y. birch available. A Limestone ledge 4' high is 48' North of  $\frac{1}{4}$  Cor. Find no mention in the record of this or of several swamp edges.

H-3 Re-established corner midway and on line bet. two Sec. Corners. Found no evidence of original corner. Corner lies in green cedar swamp.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
Placed 1" pipe with 4" aluminium cap at all corners.

G-3 New Bearings:	G-2 New Bearings:	H-3 New Bearings:
7" Cedar, S36°E, 19.1'	9" Cedar, N50°E, 20.7'	16" Cedar, South, 2.2'
6" Cedar, N51°W, 14.2'	10" Soft Maple, N80°W, 11.8'	11" Cedar, S70°E, 10.9'
7" Cedar, N41°E, 19.9'		

SIGNED BY Billy D. Buckler DATE 9/19/77  
SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

