## REMON. COR. B-11, LARKIN TWP. LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Corner Code #

REMONITMENTATION

B-11

Located in:

T 15N R 2E

For corners in

(County)

1. Public Land Survey

2. Property Controlling

Property in Sec.

Signed by Mode

Surveyor's Michigan License No. 29241

in Section
3. Miscellaneous

Midland

515

STATE OF MICHIGAN

MIDLAND COUNTY

REMONUMENTATION & FILED

12/28/2000 B:44:27 AM

SCOTT I. HAINES

Register of Deeds Stamp & File Number

REGISTER OF DEEDS

4. Lot N	
I, RODNE that under lines 1 and in the curr interior, B corner po of the Mic monumer	Y CLAYPOOL, in a field survey on May 25, 2000, do hereby certify requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on d2 above were in conformance with regulations and rules therefore as required rent manual of survey instructions of the United States Department of the ureau of Land Management or by a decree of a Court of Law and/or that the points mentioned in lines 3, 4 and 5 above were in conformance with the rules thigan Board of Land Surveyors or by a Decree of a Court of Law, re-established, need, re-monumented, recovered, found as expressed below:  Not more than 2 corners, all in the same town and range, may be recorded on this certificate.
A. Desc	cription of original monument and accessories and/or subsequent restoration:
B-11	1/4 Corner common to Sections 30 and 31
	Survey by Glo, 1830's, set post Survey by M. Hunter, 1943, found old corner set ¾ pipe Survey by M. Hunter, 1965, found Survey J. Jones, 1982, 1984, 1987, 1996, 1986, found ½ rod LCRC by D. Ledy, 1988, found ¾ pipe  Cription of corner evidence found and/or method applied in restoring or reestablishing corner:
B. Des	
B-11	1/2 Corner common to Sections 30 and 31
	Found ¾" pipe over ½" rod in ¾" pipe over ¾" pipe per surveys by M. Hunter, J. Jones and LCRC by D. Ledy
C. Des	scription of monument for corner and accessories established to perpetuate locating the position of the corner:
B-11	1/4 Corner common to Sections 30 and 31
	Replaced pipes and rod with 5/8" rod and brass cap stamped Midland Co. Remon Cor PS 29241 in monument box and is accepted as the best available evidence of the position of the original corner.
	S 50 Deg E, 35.48, nail in light pole East, 70.25, centerline gate post N 60 Deg E, 76.20, centerline gate post (Rec.) N 25 Deg E, 78.13, nail and tag in power pole (Rec.) N 45 Deg W, 52.86, spike in 18" Pine (Rec.) S 30 Deg E, 101.23, spike in 12" Pine (Rec.)

12/27/00/16

/LIFROVED LAND CORNER
P.A. 345 OF 1990
MIDLAND COUNTY

Date 12-12-00
Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Revised May 14, 1971 Revised Jan., 1983