## **GURVEY &** REMONUMENTATION

DEC 07 1994

RATIFIED	QUC		
MONROL CU	/ JHIGAN	COMMISSION	De Deuxer
date: 10 - Z	(4-2)3		RECEIVED FOR RECORD
County Rep.:	Din	LAND CORNER RECORDATION CERTIFICATE	94 OCT 12 PM 2: 13
For corners in	•	Filing Requirement of Act 74, Mich. P.A. 1970	1
MONROE (Cou	d Survey	Located In: Corner Code ##  BEDFORD TWP.  T _8 S R _7 E	REGISTER OF DEEDS MONROE COUNTY, MICH
<ol> <li>Property Control Section</li> <li>Miscellaned Property in</li> </ol>	S ous S	T	gister of Deeds Stamp & File Number
5. Private Clai	ims	d Plat	A B C D E F G H I J K L M
		ONUMENTATION PROGRAM Peer Group on 10-26-1993 per Act 345 of 1990.	3 5 4 3 2 1 1
do hereby certify in lines 1 and 2 current manual of Management or babove were in co-Court of Law; e expressed below	NKE, JR, in a fithat under requirement above were in conformations of survey instructions only a decree of a Court on formance with the rulestablished, re-established.	eld survey on SEPTEMBER 2 19 94	4 7 8 9 10 11 12 12 15 14 13 15 16 15 14 13 15 16 17 16 15 16 17 17 16 17 17 17 18 19 10 10 10 10 10 10 10 10 10 10 10 10 10
	ore than 4 corners, s certificate.	all in the same town and range, may be recorded	11 12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:  C-3, T8S, R7E, Corner at Sections 5, 6, 7 & 8  (At Secor Road & Samaria Road)  G.L.O. Surveyor Joseph Wampler set corner post in 1820. Witnesses: W. Oak 18 inch S.42°E. 40 links & B. Oak 7 inch N.08°W. 11 links. / Old book notes old stake with stone over per A.F. Winney in 1894. / A.J.M. found bolt in 1961. / M.D.O.T. Surveyor h.J. Czubak (No. 12581) found bolt and witnessed in March of 1964. M.D.O.T. Survey Chief Liubakka set boat spike in monument box in October of 1965. This point was used until when roads were re-aligned. During this construction period, George B. Warnke probed and dug for stone; but it was not found. To date, corner replaced by a 1/2 inch rebar in Description of corner evidence found and/or method applied in restoring or reestablishing corner:			
shown b	elow. 9/2/19	found 1/2 inch rebar in square top monumen 194, 1/2 inch rebar is concreted into bott . Set brass remonumentation cap on 1/2 inc	com of monument box and
C-3 - F	Set brass remo	corner and accessories established to perpetuate locating the continumentation cap on rebar in square top monument box and is ac	te position of the corner:
North 4 South 4 South 5 North 5	5° West 48.01' 0° West 53.17' 0° East 66.71' 1° East 64.26'	the position of the original corner and we mail/shiner in southwest face of utility mail/shiner in southeast face of utility mail/shiner in southwest face of blinking mail/shiner in northwest root of 24 inch notch in northeast rim of storm manhole	pole pole   traffic light guy pole
∎gned by	L.V.		BER 2, 1994
⊒rveyor's MicI	higan License No.\_	19474 FORM APPRI	DVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28. 1971

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 Revised May 14, 1975 Revised Jan., 1983