

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. <u>44</u> <sup>N.</sup> <sub>S.</sub> , R <u>23</u> <sup>E.</sup> <sub>W.</sub>		<u>J-5, K-5</u>
2. PROPERTY CONTROLLING IN SECTION <u>11</u> T. <u>44</u> <sup>N.</sup> <sub>S.</sub> , R <u>23</u> <sup>E.</sup> <sub>W.</sub>		<u>16</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____ T. _____ <sup>N.</sup> <sub>S.</sub> , R. _____ <sup>E.</sup> <sub>W.</sub>		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, David B. Babbitt do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on February 21 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_ 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- J-5 S.  $\frac{1}{4}$  Corner - Section 11; Wood Post, Tam. 20 - N2°W - 18 lks.; Birch 7 - S15°W - 10 lks.
- K-5 S.E. Section corner - Section 11; Wood Post, Cedar 12 - N55°W - 21 lks.; Birch 9 - S50°E - 11 lks.
- 16 E. 1/16 corner on the south section line of Section 11; not previously established.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- J-5 Set M.P.O.L. between the SW & SE section corners of Section 11
- K-5 Set from remains of a cedar stump down & quite rotten for the NW O.B.T.-no scribe marks visible at this time but it does show some evidence of having been scarred on the SE side. Two yellow birch are now growing in the right relative position for the original birch B.T. and are probably sprouts from the SE O.B.T. In addition, the monument falls directly in front of the base on a very old cedar signature tree SW & is very near the double proportionate position.
- 16 Set M.P.O.L. between the SE section corner and the South  $\frac{1}{4}$  corner of Section 11.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- ALL - 1" pipe, 4" aluminum cap.
- J-5 13" Y. Birch - S34°W - 33.5'; 6" Balsam - N80°W - 19.15'; 4" Cedar - North - 24.15'; 9" Cedar - S75°E - 61.6'.
- K-5 6" Cedar - N32°W - 26.6'; 8" Cedar - S79°W - 28.8'; 9" Cedar - S4°E - 19.1'; 4" Cedar - S57°E - 24.8'.
- 16 4" Cedar - S67°E - 23.65'; 13" Hemlock - S80°W - 62.55'; 6" Hemlock - N50°W - 43.95'; 6" Cedar - N23°W - 50.50'.

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY David B. Babbitt DATE 2-25-80  
CHIEF OF SURVEY PARTY  
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558