LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

| 1. Public Land Survey | |
|---|---------|
| | |
| 2. Property Controlling S T R IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII | |
| 3. Miscellaneous S T R Property in Sec. S T R | |
| 4. Lot No. , Recorded Plat 5. Private Claims Register of Deeds Stamp & Fi | I J K L |
| I, Stephan J. Szyszkoski, in a field survey on O4/19/16 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8 | 11 12 |
| NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. | 26 25 |

- A. Description of original monument and accessories and/or subsequent restoration:
- (A7) Corner common to Sections 13-24 T45N-R31W and 18-19 T45N-R30W. 1969 Reestablished by A.O.Enger RLS at a position which corresponds with the original field note calls to ridge tops east, west, north and south. Set 1"IDx36" I.pipe with 4" aluminum cap. R.Maple 8" S61°E 23 links, Balsam 9" N4 1/2°E 26 links, W.Birch 9" S68°W 22 links.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (A7) Found the 1969 monument in good condition, no evidence of the 1969 witnesses. Verified the position of the monument by coordinating with monumented A8, A9, and K7, L7 (T45N-R31W), and found it to be in accord with Mr. Enger's record with the exception of distance M7-M8, which was found to be 2412.60' (Enger=38.66 chains=2551.56'). The difference with the 1969 record appears to be the result of a measuring error by Mr. Enger made between M8 and the south shore of Little Sundog Lake, the error clearly evident in the 1969 measurement to the lakeshore when compared to aerial photography. I accepted the position of the monument as a careful and faithful reestablishment of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- (A7) Found 1"ID I.pipe with MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:

5" Sugar N32°E 19.9' 12" Maple S59°E 15.55'

mrkd "S18 NBT"

12" Maple S59°E 15.55' 7" Sugar S80°W 2.7' "S19 NBT"

3" Sugar N42°W 13.3'

"S24 NBT"
"S13 NBT"

Set sq'd cedar post adjacent.

E= 7913900.779 N= 168000.611

LAND SUR

| Department and an arranged to the second | | | | | |
|--|-----------------|------------------|--------------|---------------|----------|
| Bearings are magnetic. | Coordinates are | MCS83 in meters, | NAD83 (2011) | Epoch 2010.00 | datum. |
| Coord. Ref.= | NGS PID RL0202: | N= 156159.364 m. | E= 7917031.3 | 370 m. | aa can . |

Surveyor's Michigan License No.

- Kanszlasti

Date

04/25/2016

OF MICH

STEPHAN J

SZYSZKOSKI

LAND

JRVEYOR

For the Michigan Department of Natural Resources, Forest Resources Division