LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	_ Located In:	Corner Code #	
1. Public Land Survey	T 46N R 30W	G10 (GCDB 400240)	
2. Property Controlling in Section	T 46N R 30W S T R S T R	F11 (GCDB 340200)	
3. Miscellaneous Property in Sec.	S T R S T R S T R		
4. Lot No. , Re 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number
above were in conformance with instructions of the United States a Court of Law and for that the other rules of the Michigan Boar re-established, monumented, recov	n a field survey on F11 Off. 74, Michigan P.A. of 1970, the corner regulations and rules therefore as required Department of the Interior, Bureau of Larry points mentioned in lines 3, 4 and d of Land Surveyors or by a Decree	red in the current manual of survey and Management or by a decree of 5 above were in conformance with of a Court of Law; established, e, may be recorded	, 5 , 6 , 6 , 7

A. Description of original monument and accessories and/or subsequent restoration:

(G10) Quarter corner common to Sections 27 and 28. 1961 - Neal Sperhake RLS remonumented the corner in the original position as determined from an existing original bearing tree Tamarack 14" S28°E 101 links. Set 1"IDx36" iron pipe with aluminum Kimberly-Clark Corp. cap. W.Pine 10" S66°E 93 links, Spruce 7" S82°W 51 links.

(F11) Quarter corner common to Sections 28 and 33. 1961 - Neal Sperhake RLS reestablished the position for the corner midway and on line between Section corners 39.905 chains east and west. Set 1"IDx36" I.pipe with aluminum Kimberly-Clark Corp. cap. Maple 17" S57°E 43 links, Maple 6" N40°W 23 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G10) Found the 1961 monument in good condition and at record bearing and distance from the 1961 NBTs, now both dead and down. The OBT Tamarack was not recovered. Accepted the monument as a careful and faithful perpetuation of the position of the original corner.

(F11) Found the 1961 monument in good condition and substantially at the midway position noted in the 1961 record. The 1961 NBTs were not found. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G10) Fd. 1"ID I.pipe with alum. Kimberly-Clark Corporation cap. Set measuring nail with MDNR tag in the side of:	(F11) Fd. 1"ID I.pipe with alum. Kimberly-Clark Corporation cap. Set measuring nail with MDNR ta in the side of:	ıg
3" B.Spruce N23°E 2.1' mrkd "1/4S NBT" 4" Tamarack S78°E 19.7' do 5" Tamarack S21°E 29.5' do 4" B.Spruce S42°W 2.35' do E= 7918852.124 N= 175251.275	4" Sugar N51°E 20.8' mrkd "1/4S NBT" 5" Sugar N86°E 19.2' do 11" Sugar N73°W 14.8' do 13" Basswood N31°W 6.25' do Set sq'd cedar post adjacent. E= 7918038.528 N= 174449.848	

Bearings are magnetic.	Coordinates are	MCS83	in meters,	NAD83 (2011)	Epoch	2010.00	datum
Coord Ref -	NICE DID AMONON.	NT- 1 01	2022 600	7 5005.55			

Coord. Ref.=NGS PID AA8080: N= 192972.689 m. E= 7925456.741 m.

Signed by Stephen Saylor Date 08/11/2015

Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

STEPHAN J

SZYSZKOSK

FORM APPROVED BY MICHIGAN STATE BOARD O